

City of Millington
ADA Self-Evaluation and Transition Plan
Action Log
9/30/2019

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	5	Public Works	1	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible building entrance.	\$ 3,375.00	2	High		
Building	5	Public Works	2	The building entrance is not located on an accessible route. When a building, or portion of a building, is required to be accessible, an accessible route of travel shall be provided to all portions of the building, to accessible building entrances and to accessible parking areas.	\$ 6,750.00	2	High		
Building	11	Millington Middle School	13	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 4,725.00	2	High		
Building	11	Millington Middle School	34	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 2,025.00	2	High		
Building	11	Millington Middle School	35	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 2,025.00	2	High		
Building	11	Millington Middle School	39	The ramp projects into a prohibited area.	\$ 4,725.00	2	High		
Building	12	Millington Central High School	58	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 2,025.00	2	High		
Building	12	Millington Central High School	59	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheelchair guides, etc.).	\$ 2,025.00	2	High		
Building	12	Millington Central High School	62	The building entrance is not located on an accessible route.	\$ 3,375.00	2	High		
Building	1	County Clerk Office/Fire Station #1	1	The accessible parking stall's access aisle contains a built up curb ramp which results in significant slopes greater than 2 percent.	\$ 4,725.00	3	High		
Building	8	Millington Gym	1	There are no accessible parking stalls.	\$ 2,025.00	3	High		
Building	10	EA Harrold Elementary School	1	There are no van accessible parking stalls.	\$ 405.00	3	High		
Building	10	Millington Elementary School	2	There are not enough accessible stalls. There are (3) accessible parking stalls including (0) designated for a van.	\$ 4,050.00	3	High		
Building	10	EA Harrold Elementary School	6	There are no van accessible parking stalls.	\$ 405.00	3	High		
Building	10	Millington Elementary School	6	The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 405.00	3	High		
Building	10	EA Harrold Elementary School	7	The cross slope (narrow dimension) of the parking stall exceeds 2%.	\$ 4,050.00	3	High		
Building	10	EA Harrold Elementary School	137	The platform lift controls were not functional and did not allow for the return of the lift from the opposite (raised or lowered) position to allow for unassisted entry.	\$ 3,375.00	3	High		
Building	11	Millington Middle School	1	There are no van accessible parking stalls.	\$ 4,050.00	3	High		
Building	11	Millington Middle School	23	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	3	High		
Building	12	Millington Central High School	1	There are no van accessible parking stalls.	\$ 4,050.00	3	High		
Building	12	Millington Central High School	7	There are no accessible parking stalls.	\$ 4,050.00	3	High		
Building	12	Millington Central High School	9	There are no accessible parking stalls.	\$ 8,100.00	3	High		
Building	12	Millington Central High School	10	There are no accessible parking stalls.	\$ 12,150.00	3	High		
Building	13	Millington-Memphis Airport	1	There are no accessible parking stalls.	\$ -	3	High		
Building	1	County Clerk Office/Fire Station #1	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025.00	4	High		
Building	1	County Clerk Office/Fire Station #1	3	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025.00	4	High		
Building	1	County Clerk Office/Fire Station #1	4	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ -	4	High		
Building	4	City Hall	1	The running slope of the access aisle (long dimension) exceeds 2%.	\$ 4,050.00	4	High		
Building	4	City Hall	2	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ -	4	High		
Building	4	City Hall	3	There are not enough accessible stalls. There are (2) accessible parking stalls including (1) designated for a van. There should be a minimum of (3) accessible parking stalls including a minimum of (1) van accessible stalls.	\$ 2,025.00	4	High		
Building	4	City Hall	4	The landing at the entrance door exceeds 2% slope.	\$ 3,375.00	4	High		
Building	4	City Hall	5	The landing at the entrance door exceeds 2% slope.	\$ 3,375.00	4	High		
Building	4	City Hall	6	The landing at the entrance door exceeds 2% slope.	\$ 3,375.00	4	High		
Building	6	Baker Community Center	2	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	4	High		
Building	6	Baker Community Center	3	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	4	High		
Building	10	EA Harrold Elementary School	2	The access aisle is located so that a person with a disability is compelled to wheel or walk behind parking spaces other than their own accessible parking space.	\$ 675.00	4	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	EA Harrold Elementary School	3	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	4	High		
Building	10	Millington Elementary School	3	The running slope (long dimension) of the accessible parking stall exceeds 2%.	\$ 4,050.00	4	High		
Building	10	Millington Elementary School	4	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 675.00	4	High		
Building	10	Millington Elementary School	5	The access aisle is not a minimum 5 feet wide.	\$ 405.00	4	High		
Building	10	EA Harrold Elementary School	10	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	4	High		
Building	10	Millington Elementary School	10	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	4	High		
Building	10	EA Harrold Elementary School	14	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	10	EA Harrold Elementary School	15	The walking surface is obstructed. A 36 inch minimum clear walking surface is required.	\$ 675.00	4	High		
Building	10	Millington Elementary School	20	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%.	\$ 2,025.00	4	High		
Building	10	Millington Elementary School	23	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	4	High		
Building	10	Millington Elementary School	27	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%.	\$ 2,025.00	4	High		
Building	10	Millington Elementary School	28	The curb ramp on the accessible route contains cross slopes greater than 2% and running slopes greater than 8.33%.	\$ 2,025.00	4	High		
Building	10	Millington Elementary School	30	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 1,350.00	4	High		
Building	10	Millington Elementary School	32	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%.	\$ 675.00	4	High		
Building	10	EA Harrold Elementary School	34	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		
Building	10	Millington Elementary School	34	The detectable warnings are not the full width of the curb ramps.	\$ 405.00	4	High		
Building	10	EA Harrold Elementary School	36	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	10	EA Harrold Elementary School	37	The ramp does not have compliant handrails.	\$ 1,350.00	4	High		
Building	10	EA Harrold Elementary School	40	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		
Building	10	EA Harrold Elementary School	41	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	4	High		
Building	10	EA Harrold Elementary School	42	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		
Building	10	EA Harrold Elementary School	47	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	4	High		
Building	10	EA Harrold Elementary School	51	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	4	High		
Building	10	EA Harrold Elementary School	52	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	10	Millington Elementary School	52	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 1,350.00	4	High		
Building	10	EA Harrold Elementary School	65	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	4	High		
Building	10	EA Harrold Elementary School	66	The ramp run has not been provided with edge protection.	\$ 1,350.00	4	High		
Building	10	EA Harrold Elementary School	67	The handrails are mounted too low.	\$ 2,025.00	4	High		
Building	10	EA Harrold Elementary School	79	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025.00	4	High		
Building	11	Millington Middle School	2	The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 405.00	4	High		
Building	11	Millington Middle School	3	The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 405.00	4	High		
Building	11	Millington Middle School	11	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	4	High		
Building	11	Millington Middle School	12	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	11	Millington Middle School	24	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 4,050.00	4	High		
Building	11	Millington Middle School	25	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675.00	4	High		
Building	11	Millington Middle School	26	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		
Building	11	Millington Middle School	27	The ramp run has not been provided with edge protection.	\$ 405.00	4	High		
Building	11	Millington Middle School	28	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	11	Millington Middle School	29	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		
Building	11	Millington Middle School	30	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	11	Millington Middle School	31	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		
Building	11	Millington Middle School	32	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	4	High		
Building	11	Millington Middle School	36	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 270.00	4	High		
Building	11	Millington Middle School	37	The drain pipe projects more than 4 inches into the circulation path.	\$ 270.00	4	High		
Building	11	Millington Middle School	38	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 270.00	4	High		
Building	11	Millington Middle School	91	No wheelchair seating is provided at the bleacher seating areas.	\$ 4,050.00	4	High		
Building	11	Millington Middle School	100	The restroom is not nearly compliant.	\$ 14,850.00	4	High		
Building	11	Millington Middle School	101	The restroom is not nearly compliant.	\$ 14,850.00	4	High		
Building	12	Millington Central High School	2	The running slope of the access aisle (long dimension) exceeds 2%.	\$ 4,050.00	4	High		
Building	12	Millington Central High School	3	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ -	4	High		
Building	12	Millington Central High School	6	The running slope (long dimension) of the accessible parking stall exceeds 2%.	\$ 4,050.00	4	High		
Building	12	Millington Central High School	23	The curb ramp on the accessible route contains cross slopes greater than 2%.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	24	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	40	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	42	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	4	High		
Building	12	Millington Central High School	43	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	44	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	45	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	47	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	48	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	49	The accessible path of travel contains cross slopes greater than 2%.	\$ 3,375.00	4	High		
Building	12	Millington Central High School	56	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,700.00	4	High		
Building	12	Millington Central High School	61	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	64	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	65	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	4	High		
Building	12	Millington Central High School	67	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	4	High		
Building	12	Millington Central High School	69	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	1	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	2	The access aisle is missing at the accessible parking stall.	\$ -	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	3	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	4	The access aisle is missing at the accessible parking stall.	\$ -	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	5	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	6	The access aisle is missing at the accessible parking stall.	\$ -	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	7	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	16	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	3	High		
Park	2	Biloxi Fields/Miles Baseball Park	62	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	3	High		
Park	3	Centennial Park	1	There are no accessible parking stalls.	\$ 4,050.00	3	High		
Park	3	Centennial Park	2	There are no accessible parking stalls.	\$ 4,050.00	3	High		
Park	3	Centennial Park	3	There are no accessible parking stalls.	\$ 4,050.00	3	High		
Park	4	Joyner Fields	27	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall.	\$ 3,375.00	3	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	7	Millington Farmers Market	1	The surfaces of the accessible parking spaces and access aisles are not firm, stable, and slip resistant.	\$ -	3	High		
Park	7	Millington Farmers Market	3	The ramp's slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 1,350.00	3	High		
Park	7	Millington Farmers Market	6	The ramp's slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 1,350.00	3	High		
Park	7	Millington Farmers Market	10	The ramp's slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 1,350.00	3	High		
Park	1	Aycock Park	41	There are not enough accessible stalls. There are (4) accessible parking stalls including (0) designated for a van. There should be a minimum of (5) accessible parking stalls including a minimum of (1) van accessible stalls.	\$ 2,025.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	8	The cross slope (narrow dimension) of the parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	9	The cross slope (narrow dimension) of the parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	10	The cross slope (narrow dimension) of the parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	11	The cross slope (narrow dimension) of the parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	12	The cross slope (narrow dimension) of the parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	13	The cross slope (narrow dimension) of the parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	15	The running slope (long dimension) of the accessible parking stall exceeds 2%. The running slope in an accessible parking stall and the access aisle must not exceed 2%.	\$ 3,375.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	63	The accessible parking is not located on the shortest accessible route to the parking facility entrance.	\$ 8,100.00	4	High		
Park	2	Biloxi Fields/Miles Baseball Park	65	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 6,750.00	4	High		
Park	3	Centennial Park	5	The walking surface is obstructed. A 36 inch minimum clear walking surface is required.	\$ 2,025.00	4	High		
Park	5	Lions Park Pavilion	4	The running slope (long dimension) of the accessible parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	5	Lions Park Pavilion	5	The running slope (long dimension) of the accessible parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	5	Lions Park Pavilion	6	The running slope (long dimension) of the accessible parking stall exceeds 2%.	\$ 4,050.00	4	High		
Park	5	Lions Park Pavilion	7	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	4	High		
Park	5	Lions Park Pavilion	8	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	4	High		
Park	5	Lions Park Pavilion	9	The access aisle is missing at the accessible parking stall.	\$ 2,700.00	4	High		
ROW Sidewalk	1	King Station Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,009.90	1	High		
ROW Sidewalk	2	Kelsey Lauren Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,604.05	1	High		
ROW Sidewalk	3	Queen Sinclair Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,618.81	1	High		
ROW Sidewalk	4	Pleasant Ridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,188.86	1	High		
ROW Sidewalk	5	Raleigh Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,623.66	1	High		
ROW Sidewalk	6	Pleasant Ridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 37,703.59	1	High		
ROW Sidewalk	7	Julia Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 44,457.74	1	High		
ROW Sidewalk	8	Zachary St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 42,888.34	1	High		
ROW Sidewalk	9	Colorday Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,086.71	1	High		
ROW Sidewalk	10	Eckois Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,549.18	1	High		
ROW Sidewalk	11	Tywaip Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,162.31	1	High		
ROW Sidewalk	12	Nichols Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,937.14	1	High		
ROW Sidewalk	13	Jeffery St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 41,155.40	1	High		
ROW Sidewalk	14	Ellen St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,021.58	1	High		
ROW Sidewalk	15	Annie Lee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 34,954.93	1	High		
ROW Sidewalk	16	Angie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,890.19	1	High		
ROW Sidewalk	17	Misslow Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,630.84	1	High		
ROW Sidewalk	18	Jack Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,800.96	1	High		
ROW Sidewalk	19	Barclay St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,663.09	1	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	20	Karista St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 39,174.25	1	High		
ROW Sidewalk	21	Emmit St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,627.10	1	High		
ROW Sidewalk	22	Goldsby Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,559.11	1	High		
ROW Sidewalk	23	Cassell Dr / Juana Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 29,772.48	1	High		
ROW Sidewalk	24	Baywood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 53,460.44	1	High		
ROW Sidewalk	25	Tickle View Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 89,518.71	1	High		
ROW Sidewalk	26	Cedar Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 75,679.28	1	High		
ROW Sidewalk	27	Clear Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 62,976.71	1	High		
ROW Sidewalk	28	Clear Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 42,210.64	1	High		
ROW Sidewalk	29	Cedar Hills Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,880.87	1	High		
ROW Sidewalk	30	Black Gum Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,555.17	1	High		
ROW Sidewalk	31	S Honeysuckle Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,874.64	1	High		
ROW Sidewalk	32	Vincent Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 63,374.12	1	High		
ROW Sidewalk	33	Tamarack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 29,338.95	1	High		
ROW Sidewalk	34	Hallbrook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 67,591.32	1	High		
ROW Sidewalk	35	Warcross Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 88,956.16	1	High		
ROW Sidewalk	36	Waycross Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,339.07	1	High		
ROW Sidewalk	37	Cades Brook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 102,581.39	1	High		
ROW Sidewalk	38	Cades Brook Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,872.71	1	High		
ROW Sidewalk	39	Cold Springs Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 84,866.49	1	High		
ROW Sidewalk	40	Richard Wilson Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130,413.02	1	High		
ROW Sidewalk	41	Saddlebrook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 78,404.27	1	High		
ROW Sidewalk	42	Juana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 104,855.49	1	High		
ROW Sidewalk	43	Quay Hill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 56,277.10	1	High		
ROW Sidewalk	44	Pam Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 105,848.63	1	High		
ROW Sidewalk	45	Alder Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,390.69	1	High		
ROW Sidewalk	46	Alder Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 59,829.78	1	High		
ROW Sidewalk	47	Oak Harbor Trce	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,292.21	1	High		
ROW Sidewalk	48	Balsa Glenn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,526.26	1	High		
ROW Sidewalk	49	Gunlock Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40,172.56	1	High		
ROW Sidewalk	50	Blue Hills St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,934.76	1	High		
ROW Sidewalk	51	Sassy Tree Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 27,508.30	1	High		
ROW Sidewalk	52	W Honeysuckle Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,298.13	1	High		
ROW Sidewalk	53	Raleigh Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 325,309.20	1	High		
ROW Sidewalk	54	Prather St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,605.05	1	High		
ROW Sidewalk	55	Juana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 147,673.42	1	High		
ROW Sidewalk	56	Hallbrook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,512.53	1	High		
ROW Sidewalk	57	Pam Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 48,494.90	1	High		
ROW Sidewalk	58	Renda St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 65,389.46	1	High		
ROW Sidewalk	59	Baker St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 74,743.50	1	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	60	Shella St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 131,861.08	1	High		
ROW Sidewalk	61	Dawson Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,972.13	1	High		
ROW Sidewalk	62	Thornhill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,621.25	1	High		
ROW Sidewalk	63	Big Creek Church Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 28,904.21	1	High		
ROW Sidewalk	64	Ryan Hill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 36,128.93	1	High		
ROW Sidewalk	65	Alexander Hill Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,616.92	1	High		
ROW Sidewalk	66	Bucknell Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,001.32	1	High		
ROW Sidewalk	67	Autumn Sun Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 91,512.85	1	High		
ROW Sidewalk	68	Eagles Hunt Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 71,529.16	1	High		
ROW Sidewalk	69	Bennett Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 141,487.53	1	High		
ROW Sidewalk	70	Water Briar Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 134,467.32	1	High		
ROW Sidewalk	71	Logan's Path Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 37,589.30	1	High		
ROW Sidewalk	72	Oak Spring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 29,881.25	1	High		
ROW Sidewalk	73	Mary Lynn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 85,753.78	1	High		
ROW Sidewalk	74	Field Oak Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 116,233.75	1	High		
ROW Sidewalk	75	Tumbling Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 74,571.02	1	High		
ROW Sidewalk	76	Hickory Meadow	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 71,576.53	1	High		
ROW Sidewalk	77	Sweet Bark Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,557.74	1	High		
ROW Sidewalk	78	Trading Post Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 29,036.92	1	High		
ROW Sidewalk	79	Quito Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 55,150.27	1	High		
ROW Sidewalk	80	Oak Pebble Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,949.62	1	High		
ROW Sidewalk	81	Oak Pebble Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,736.45	1	High		
ROW Sidewalk	82	Quito Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,225.09	1	High		
ROW Sidewalk	83	Mary Lynn Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,083.64	1	High		
ROW Sidewalk	84	Chestnut Oak Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,620.78	1	High		
ROW Sidewalk	85	Oak Spring Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,626.11	1	High		
ROW Sidewalk	86	Babe Howard Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 41,421.01	1	High		
ROW Sidewalk	87	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 169,149.18	1	High		
ROW Sidewalk	88	Arapaho St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 51,746.20	1	High		
ROW Sidewalk	89	Tecumseh St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 38,080.29	1	High		
ROW Sidewalk	90	Wampum Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,426.27	1	High		
ROW Sidewalk	91	Kiowa St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,586.31	1	High		
ROW Sidewalk	92	Bill Knight Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 91,923.90	1	High		
ROW Sidewalk	93	Newport Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 98,690.15	1	High		
ROW Sidewalk	94	Biloxi St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 57,700.00	1	High		
ROW Sidewalk	95	Rockford Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 137,854.22	1	High		
ROW Sidewalk	96	Doris Cir/ Saratoga Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 288,886.28	1	High		
ROW Sidewalk	97	Doris Cir/ Montgomery Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 242,845.14	1	High		
ROW Sidewalk	98	Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 295,874.74	1	High		
ROW Sidewalk	99	Church St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 106,411.19	1	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	100	Raleigh Millington Rd/ Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 78,056.62	1	High		
ROW Sidewalk	101	Raleigh Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 63,478.96	1	High		
ROW Sidewalk	102	Salley Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,470.05	1	High		
ROW Sidewalk	103	Shelby Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,405.41	1	High		
ROW Sidewalk	104	Martha St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 57,060.06	1	High		
ROW Sidewalk	105	Talley Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 35,383.27	1	High		
ROW Sidewalk	106	Susan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,849.76	1	High		
ROW Sidewalk	107	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 196,287.35	1	High		
ROW Sidewalk	108	Easley Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 157,875.98	1	High		
ROW Sidewalk	109	Janie Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 34,922.16	1	High		
ROW Sidewalk	110	Newport St/ Newport Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 156,430.25	1	High		
ROW Sidewalk	112	Janie Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,781.16	1	High		
ROW Sidewalk	113	Jean Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,025.38	1	High		
ROW Sidewalk	114	Nelson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 42,600.44	1	High		
ROW Sidewalk	115	Laraine Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,312.77	1	High		
ROW Sidewalk	116	Harrold Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 47,556.04	1	High		
ROW Sidewalk	118	Buford Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 67,765.61	1	High		
ROW Sidewalk	119	Pryor St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,498.03	1	High		
ROW Sidewalk	120	Church St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,893.98	1	High		
ROW Sidewalk	121	School Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,616.36	1	High		
ROW Sidewalk	122	Quinn Circle	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,751.68	1	High		
ROW Sidewalk	123	C St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 47,831.36	1	High		
ROW Sidewalk	124	Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 48,253.36	1	High		
ROW Sidewalk	125	Easley Ave/ Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,635.93	1	High		
ROW Sidewalk	126	Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 181,682.48	1	High		
ROW Sidewalk	127	W Navy Circle	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 441,179.02	1	High		
ROW Sidewalk	128	W National St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,078.85	1	High		
ROW Sidewalk	129	E National St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 159,935.33	1	High		
ROW Sidewalk	130	S Navy Circle	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 55,436.42	1	High		
ROW Sidewalk	131	Veterans Pky	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 54,467.41	1	High		
ROW Sidewalk	132	Dakar Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,148.86	1	High		
ROW Sidewalk	133	Astoria Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,409.45	1	High		
ROW Sidewalk	134	3rd Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,191.13	1	High		
ROW Sidewalk	135	B St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 121,594.72	1	High		
ROW Sidewalk	136	A St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,424.15	1	High		
ROW Sidewalk	137	School Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 43,324.46	1	High		
ROW Sidewalk	138	Wilkinsville Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 158,382.09	1	High		
ROW Sidewalk	139	Second Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,827.90	1	High		
ROW Sidewalk	140	North Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 57,516.27	1	High		
ROW Sidewalk	141	Cuba Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50,061.11	1	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	142	West St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 82,272.40	1	High		
ROW Sidewalk	143	Chambers St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 44,475.66	1	High		
ROW Sidewalk	144	Second Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 115,700.72	1	High		
ROW Sidewalk	145	Bland Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 73,653.36	1	High		
ROW Sidewalk	146	Hill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,384.74	1	High		
ROW Sidewalk	147	First Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 99,048.76	1	High		
ROW Sidewalk	148	Cuba Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30,384.03	1	High		
ROW Sidewalk	149	Densford Circle W	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,238.58	1	High		
ROW Sidewalk	150	Densford Circle E	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,811.23	1	High		
ROW Sidewalk	151	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 153,033.88	1	High		
ROW Sidewalk	152	Glencoe Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,571.79	1	High		
ROW Sidewalk	153	Wilkinsville Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,538.21	1	High		
ROW Sidewalk	154	Cooper Creek Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,653.45	1	High		
ROW Sidewalk	155	Creek Mill Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,571.98	1	High		
ROW Sidewalk	156	End Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,508.76	1	High		
ROW Sidewalk	157	Terrell Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,557.05	1	High		
ROW Sidewalk	158	Wells Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,839.19	1	High		
ROW Sidewalk	159	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,284.69	1	High		
ROW Sidewalk	160	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 53,517.75	1	High		
ROW Sidewalk	161	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,216.39	1	High		
ROW Sidewalk	162	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30,849.46	1	High		
ROW Sidewalk	163	Church St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,744.52	1	High		
ROW Sidewalk	164	Union Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 46,666.70	1	High		
Signalized Intersection	2	Intersection of Church St and Easley Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Church St and Easley Ave	\$ 88,000.00	2	High		
Signalized Intersection	6	Intersection of Navy Rd and Astoria Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Astoria Rd	\$ 103,800.00	2	High		
Signalized Intersection	14	Intersection of Veterans Pkwy and Hwy 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Veterans Pkwy and Hwy 51	\$ 96,500.00	2	High		
Signalized Intersection	4	Intersection of Cuba Millington Rd and Hwy 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cuba Millington Rd and Hwy 51	\$ 115,900.00	4	High		
Signalized Intersection	5	Intersection of Micro Dr and Hwy 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Micro Dr and Hwy 51	\$ 49,300.00	4	High		
Unsignalized Intersection	1065	Intersection of Raleigh Millington Rd and Oak Harbour Trce	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Oak Harbour Trce	\$ 41,400.00	2	High		
Unsignalized Intersection	1076	Intersection of Raleigh Millington Rd and Big Creek Church Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Big Creek Church Rd	\$ 56,200.00	2	High		
Unsignalized Intersection	1079	Intersection of Raleigh Millington Rd and Hallbrook Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Hallbrook Dr	\$ 57,900.00	2	High		
Unsignalized Intersection	1084	Intersection of Raleigh Millington Rd and Waycross Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Waycross Ave	\$ 45,700.00	2	High		
Unsignalized Intersection	1093	Intersection of Renda St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Renda St and driveway	\$ 4,900.00	2	High		
Unsignalized Intersection	1141	Intersection of Church St and Montgomery Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Church St and Montgomery Rd	\$ 45,600.00	2	High		
Unsignalized Intersection	1198	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 5,600.00	2	High		
Unsignalized Intersection	1204	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 7,100.00	2	High		
Unsignalized Intersection	1206	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 4,400.00	2	High		
Unsignalized Intersection	1207	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 4,400.00	2	High		
Unsignalized Intersection	1210	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 2,200.00	2	High		
Unsignalized Intersection	1216	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 20,700.00	2	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Unsignalized Intersection	1219	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 12,500.00	2	High		
Unsignalized Intersection	1261	Intersection of Nelson St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Nelson St and driveway	\$ 7,500.00	2	High		
Unsignalized Intersection	1265	Intersection of Church St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Church St and driveway	\$ 3,200.00	2	High		
Unsignalized Intersection	1273	Intersection of Church St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Church St and driveway	\$ 5,600.00	2	High		
Unsignalized Intersection	1277	Intersection of Nelson St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Nelson St and driveway	\$ 11,200.00	2	High		
Unsignalized Intersection	1292	Intersection of Easley Ave and C St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and C St	\$ 65,400.00	2	High		
Unsignalized Intersection	1296	Intersection of Nelson St and Newport St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Nelson St and Newport St	\$ 44,000.00	2	High		
Unsignalized Intersection	1332	Intersection of Easley Ave and West St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and West St	\$ 42,600.00	2	High		
Unsignalized Intersection	1334	Intersection of Easley Ave and Chambers St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and Chambers St	\$ 53,300.00	2	High		
Unsignalized Intersection	1335	Intersection of Easley Ave and Laraine Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and Laraine Dr	\$ 32,700.00	2	High		
Unsignalized Intersection	1347	Intersection of West St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of West St and driveway	\$ 2,900.00	2	High		
Unsignalized Intersection	1352	Intersection of School Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of School Ave and driveway	\$ 5,100.00	2	High		
Unsignalized Intersection	1354	Intersection of School Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of School Ave and driveway	\$ 4,500.00	2	High		
Unsignalized Intersection	1356	Intersection of Wilkinsville Rd and School Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and School Ave	\$ 30,300.00	2	High		
Unsignalized Intersection	1367	Intersection of Second Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Second Ave and driveway	\$ 4,900.00	2	High		
Unsignalized Intersection	1371	Intersection of Highway 51 and Second Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and Second Ave	\$ 48,800.00	2	High		
Unsignalized Intersection	1372	Intersection of West St and Second Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of West St and Second Ave	\$ 38,800.00	2	High		
Unsignalized Intersection	1374	Intersection of Wilkinsville Rd and Second Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and Second Ave	\$ 44,800.00	2	High		
Unsignalized Intersection	1383	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 14,100.00	2	High		
Unsignalized Intersection	1385	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 16,600.00	2	High		
Unsignalized Intersection	1393	Intersection of Wilkinsville Rd and Howard Pl	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and Howard Pl	\$ 8,900.00	2	High		
Unsignalized Intersection	1396	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 11,900.00	2	High		
Unsignalized Intersection	1399	Intersection of Cuba Millington Rd and Wilkinsville Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cuba Millington Rd and Wilkinsville Rd	\$ 40,500.00	2	High		
Unsignalized Intersection	1401	Intersection of Cuba Millington Rd and West St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cuba Millington Rd and West St	\$ 51,300.00	2	High		
Unsignalized Intersection	1411	Intersection of Cuba Millington Rd and Densford Circle W	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cuba Millington Rd and Densford Circle W	\$ 48,400.00	2	High		
Unsignalized Intersection	1433	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 31,600.00	2	High		
Unsignalized Intersection	1453	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 23,600.00	2	High		
Unsignalized Intersection	1455	Intersection of Cooper Creek Blvd and Highway 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cooper Creek Blvd and Highway 51	\$ 54,800.00	2	High		
Unsignalized Intersection	90081	Intersection of Cuba Millington Rd and Densford Circle E	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cuba Millington Rd and Densford Circle E	\$ 28,600.00	2	High		
Unsignalized Intersection	90088	Intersection of West Union Rd and Creek Mill Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of West Union Rd and Creek Mill Rd	\$ 48,200.00	2	High		
Unsignalized Intersection	90091	Intersection of Hwy 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and driveway	\$ 15,200.00	2	High		
Unsignalized Intersection	90092	Intersection of Hwy 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and driveway	\$ 6,800.00	2	High		
Unsignalized Intersection	90118	Intersection of Bill Knight and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bill Knight and driveway	\$ 12,500.00	2	High		
Unsignalized Intersection	90121	Intersection of West St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of West St and driveway	\$ 20,000.00	2	High		
Unsignalized Intersection	90122	Intersection of West St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of West St and driveway	\$ 7,200.00	2	High		
Unsignalized Intersection	90123	Intersection of Second Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Second Ave and driveway	\$ 6,800.00	2	High		
Unsignalized Intersection	90124	Intersection of Second Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Second Ave and driveway	\$ 7,200.00	2	High		
Unsignalized Intersection	90127	Intersection of Second Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Second Ave and driveway	\$ 1,600.00	2	High		
Unsignalized Intersection	90133	Intersection of Chambers St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Chambers St and driveway	\$ 9,900.00	2	High		
Unsignalized Intersection	90145	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 12,500.00	2	High		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Unsignalized Intersection	90146	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 15,300.00	2	High		
Unsignalized Intersection	1119	Intersection of Biloxi St and Newport Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Biloxi St and Newport Rd	\$ 26,700.00	3	High		
Unsignalized Intersection	1218	Intersection of Harrold Cv and Harrold Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Harrold Cv and Harrold Dr	\$ 53,200.00	3	High		
Unsignalized Intersection	1280	Intersection of Buford Ave and Church St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Buford Ave and Church St	\$ 15,700.00	3	High		
Unsignalized Intersection	1320	Intersection of 3rd Ave and B St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of 3rd Ave and B St	\$ 50,600.00	3	High		
Unsignalized Intersection	1329	Intersection of Talley Rd and Martha St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Talley Rd and Martha St	\$ 25,800.00	3	High		
Unsignalized Intersection	1331	Intersection of Easley Ave and Harrold Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and Harrold Dr	\$ 38,400.00	3	High		
Unsignalized Intersection	1333	Intersection of Wilkinsville Rd and A St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and A St	\$ 13,200.00	3	High		
Unsignalized Intersection	1350	Intersection of Wilkinsville Rd and School Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and School Ave	\$ 25,500.00	3	High		
Unsignalized Intersection	1357	Intersection of Shelby Rd and Martha St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Shelby Rd and Martha St	\$ 40,000.00	3	High		
Unsignalized Intersection	1376	Intersection of Bland Ave and West St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bland Ave and West St	\$ 38,200.00	3	High		
Unsignalized Intersection	1382	Intersection of Hill St and Bland Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hill St and Bland Ave	\$ 31,500.00	3	High		
Unsignalized Intersection	1388	Intersection of West St and First Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of West St and First Ave	\$ 50,500.00	3	High		
Unsignalized Intersection	1392	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 54,200.00	3	High		
Unsignalized Intersection	1403	Intersection of Wilkinsville Rd and North Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and North Ave	\$ 38,200.00	3	High		
Unsignalized Intersection	90098	Intersection of Nelson St and Second Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Nelson St and Second Ave	\$ 38,900.00	3	High		
Building	1	County Clerk Office/Fire Station #1	5	The landing at the entrance door exceeds 2% slope.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	6	Neither leaves of the doorways provide at least 32 inches between the face of the door and the opposite stop. At least one of the active leaves of doorways with two leaves shall comply with clear width and maneuvering clearance. Door openings shall	\$ 4,725.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	7	All automatic and power-assisted doors must comply with Builders Hardware Manufacturers' Association A156.10 or low energy operated doors complying with BHMA A156.19.	\$ 1,350.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	8	The transaction counter is too high.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	9	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	10	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	14	All automatic and power-assisted doors must comply with Builders Hardware Manufacturers' Association A156.10 or low energy operated doors complying with BHMA A156.19.	\$ 1,350.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	16	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	17	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	18	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	19	The restroom is not nearly compliant.	\$ 13,500.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	21	The transaction counter is too high.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	22	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	23	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	24	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	25	The restroom is not nearly compliant.	\$ 13,500.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	26	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	27	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	28	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	29	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	30	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	31	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	33	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	35	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	1	County Clerk Office/Fire Station #1	36	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	37	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	39	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	40	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	41	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 6,750.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	42	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	43	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	44	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	45	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	1	County Clerk Office/Fire Station #1	48	The door/gate operating hardware is not accessible.	\$ 1,350.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	49	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	50	The restroom is not nearly compliant.	\$ 13,500.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	51	The door/gate operating hardware is not accessible.	\$ 1,350.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	53	The restroom is not nearly compliant.	\$ 13,500.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	56	There is no accessible route to the (front entrance).	\$ 4,725.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	57	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 4,725.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	60	The restroom is not nearly compliant.	\$ 10,125.00	5	Medium		
Building	2	Police Station - Jail - Courts	7	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	2	Police Station - Jail - Courts	11	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	2	Police Station - Jail - Courts	14	The transaction counter is too high.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	16	The restroom is not nearly compliant.	\$ 10,125.00	5	Medium		
Building	2	Police Station - Jail - Courts	17	The door exceeds the maximum pressure to open the door.	\$ 135.00	5	Medium		
Building	2	Police Station - Jail - Courts	18	The door exceeds the maximum pressure to open the door.	\$ 135.00	5	Medium		
Building	2	Police Station - Jail - Courts	20	The restroom is not nearly compliant.	\$ 10,125.00	5	Medium		
Building	2	Police Station - Jail - Courts	21	The door/gate operating hardware is not accessible.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	24	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	26	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	28	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	29	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	30	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	2	Police Station - Jail - Courts	33	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	38	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	41	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	43	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	47	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	48	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	50	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	2	Police Station - Jail - Courts	57	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	59	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	65	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	2	Police Station - Jail - Courts	66	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	68	The door/gate operating hardware is not accessible.	\$ 1,687.50	5	Medium		
Building	2	Police Station - Jail - Courts	74	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	75	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	76	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	77	The door/gate operating hardware is not accessible.	\$ 1,350.00	5	Medium		
Building	2	Police Station - Jail - Courts	79	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	2	Police Station - Jail - Courts	82	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	2	Police Station - Jail - Courts	86	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	2	Police Station - Jail - Courts	87	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	88	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	90	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	2	Police Station - Jail - Courts	91	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	95	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	97	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	99	The door/gate operating hardware is not accessible.	\$ 1,687.50	5	Medium		
Building	2	Police Station - Jail - Courts	102	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	107	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	2	Police Station - Jail - Courts	108	The transaction counter is too high.	\$ 3,375.00	5	Medium		
Building	2	Police Station - Jail - Courts	109	The (water fountain) projects more than 4 inches into the circulation path.	\$ 675.00	5	Medium		
Building	2	Police Station - Jail - Courts	110	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	3	Millington Public Library	4	The door/gate operating hardware is not accessible.	\$ 1,350.00	5	Medium		
Building	3	Millington Public Library	6	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	3	Millington Public Library	11	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	3	Millington Public Library	15	The transaction counter is too high.	\$ 675.00	5	Medium		
Building	3	Millington Public Library	16	The transaction counter is too high.	\$ 3,375.00	5	Medium		
Building	3	Millington Public Library	17	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	3	Millington Public Library	22	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	3	Millington Public Library	23	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	3	Millington Public Library	24	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	3	Millington Public Library	29	The controls are located such that operation require reaching across burners.	\$ 3,375.00	5	Medium		
Building	3	Millington Public Library	30	The (hood vent control) is positioned too high for either a side or front approach. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor	\$ 675.00	5	Medium		
Building	4	City Hall	9	The door/gate operating hardware is not accessible.	\$ 2,362.50	5	Medium		
Building	4	City Hall	10	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	4	City Hall	13	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	4	City Hall	25	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	5	Medium		
Building	4	City Hall	34	Based on the number of seats provided in this area (90), there should be a minimum of (2) wheelchair seating spaces.	\$ 3,375.00	5	Medium		
Building	4	City Hall	35	There is no accessible route to the (council seating).	\$ 3,375.00	5	Medium		
Building	4	City Hall	36	The restroom is not nearly compliant.	\$ 10,125.00	5	Medium		
Building	4	City Hall	37	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	4	City Hall	38	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	4	City Hall	39	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	4	City Hall	40	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	4	City Hall	41	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	4	City Hall	44	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	4	City Hall	45	The door/gate operating hardware is not accessible.	\$ 675.00	5	Medium		
Building	4	City Hall	46	The controls are located such that operation require reaching across burners.	\$ 3,375.00	5	Medium		
Building	4	City Hall	49	The (hood vent controls) are positioned too high for either a side or front approach.	\$ 675.00	5	Medium		
Building	4	City Hall	52	The restrooms is not nearly compliant.	\$ 10,125.00	5	Medium		
Building	4	City Hall	53	The restrooms is not nearly compliant.	\$ 10,125.00	5	Medium		
Building	4	City Hall	54	The restroom is not nearly compliant.	\$ 6,750.00	5	Medium		
Building	4	City Hall	55	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	5	Public Works	3	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	5	Public Works	4	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 337.50	5	Medium		
Building	5	Public Works	5	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	5	Public Works	6	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	5	Public Works	7	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	5	Public Works	8	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	5	Public Works	9	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	5	Public Works	10	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	5	Public Works	11	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	5	Public Works	12	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	5	Public Works	13	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	5	Public Works	14	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	5	Public Works	16	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	5	Public Works	18	The door/gate operating hardware is not accessible.	\$ 337.50	5	Medium		
Building	5	Public Works	19	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	6	Baker Community Center	15	There is no accessible route to the stage.	\$ 2,025.00	5	Medium		
Building	6	Baker Community Center	17	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	6	Baker Community Center	18	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	6	Baker Community Center	22	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Building	6	Baker Community Center	24	The kitchen counter top is too high.	\$ 2,025.00	5	Medium		
Building	6	Baker Community Center	33	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	6	Baker Community Center	43	The transaction counter provides for a parallel approach and is not within the required height range.	\$ 2,025.00	5	Medium		
Building	6	Baker Community Center	47	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	6	Baker Community Center	50	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	6	Baker Community Center	54	The door exceeds the maximum pressure to open the door.	\$ 135.00	5	Medium		
Building	7	USA Stadium Complex	42	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	7	USA Stadium Complex	44	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	7	USA Stadium Complex	49	The dugout is not on an accessible route.	\$ 2,025.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	7	USA Stadium Complex	50	There is no accessible route to the bullpen.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	51	The dugout is not on an accessible route.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	52	There is no accessible route to the bullpen.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	62	The wheelchair seating spaces are not on an accessible route.	\$ 3,375.00	5	Medium		
Building	7	USA Stadium Complex	69	The threshold is greater than 1/2 inch high.	\$ 675.00	5	Medium		
Building	7	USA Stadium Complex	70	The maneuvering space on the pull side of the door or gate does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	7	USA Stadium Complex	76	The maneuvering space on the pull side of the door or gate does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	7	USA Stadium Complex	79	The maneuvering space on the pull side of the door or gate does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	7	USA Stadium Complex	85	The threshold is greater than 1/2 inch high.	\$ 675.00	5	Medium		
Building	7	USA Stadium Complex	86	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	7	USA Stadium Complex	87	The controls are located such that operation require reaching across burners.	\$ 3,375.00	5	Medium		
Building	7	USA Stadium Complex	89	The transaction counter is too high.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	90	The dryer control is positioned too high for either a side or front approach.	\$ 3,375.00	5	Medium		
Building	7	USA Stadium Complex	91	The door/gate operating hardware is not accessible.	\$ 1,518.75	5	Medium		
Building	7	USA Stadium Complex	94	The maneuvering space on the pull side of the door or gate does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	7	USA Stadium Complex	105	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	112	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	7	USA Stadium Complex	114	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	7	USA Stadium Complex	122	The ramp's slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	125	There is no accessible route to the restroom.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	134	The ramp's slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	137	There is no accessible route to the restroom.	\$ -	5	Medium		
Building	7	USA Stadium Complex	148	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	7	USA Stadium Complex	149	There is a change in level greater than 1/4 inch.	\$ 2,025.00	5	Medium		
Building	7	USA Stadium Complex	151	There is no accessible route to the ramp.	\$ 2,025.00	5	Medium		
Building	8	Millington Gym	2	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		
Building	8	Millington Gym	3	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	8	Millington Gym	4	The threshold is greater than 1/2 inch high.	\$ 675.00	5	Medium		
Building	8	Millington Gym	18	The door exceeds the maximum pressure to open the door.	\$ 135.00	5	Medium		
Building	8	Millington Gym	19	The maneuvering clearance on the pull side of the door is not long enough in the direction of travel.	\$ 3,375.00	5	Medium		
Building	8	Millington Gym	26	The door exceeds the maximum pressure to open the door.	\$ 135.00	5	Medium		
Building	8	Millington Gym	27	The maneuvering clearance on the pull side of the door is not long enough in the direction of travel.	\$ 3,375.00	5	Medium		
Building	8	Millington Gym	34	The door locking mechanism requires tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	5	Medium		
Building	8	Millington Gym	35	The maneuvering space on the pull side of the door or gate does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	8	Millington Gym	43	The door locking mechanism requires tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	5	Medium		
Building	8	Millington Gym	44	The light switch is positioned too high for either a side or front approach.	\$ 270.00	5	Medium		
Building	10	EA Harrold Elementary School	11	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	12	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	13	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	EA Harrold Elementary School	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	10	EA Harrold Elementary School	18	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	19	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	20	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	21	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	22	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	23	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	24	The ramp landing has not been provided with edge protection.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	25	The ramp does not have compliant handrails.	\$ 675.00	5	Medium		
Building	10	EA Harrold Elementary School	26	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	29	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	32	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	35	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	10	EA Harrold Elementary School	38	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	39	The ramp run has not been provided with edge protection.	\$ 1,350.00	5	Medium		
Building	10	EA Harrold Elementary School	44	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	45	There is no accessible route to the flagpole.	\$ 2,025.00	5	Medium		
Building	10	Millington Elementary School	47	There is no accessible route to the playground.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	49	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	10	EA Harrold Elementary School	50	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	10	EA Harrold Elementary School	53	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	55	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	56	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	Millington Elementary School	56	There is no accessible route to the playground.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	57	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	58	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	Millington Elementary School	58	There is no accessible route to the playground.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	60	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	61	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	63	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	10	EA Harrold Elementary School	64	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	10	Millington Elementary School	64	The landing of the ramp has a slope greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	68	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	69	The handrail is not continuous the entire length of the ramp.	\$ 1,350.00	5	Medium		
Building	10	EA Harrold Elementary School	70	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	71	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,350.00	5	Medium		
Building	10	EA Harrold Elementary School	72	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	73	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	10	EA Harrold Elementary School	74	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	75	The ramp does not have compliant handrails.	\$ 2,025.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	EA Harrold Elementary School	76	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	80	The ramp run has not been provided with edge protection.	\$ 675.00	5	Medium		
Building	10	EA Harrold Elementary School	81	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	83	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 202.50	5	Medium		
Building	10	EA Harrold Elementary School	84	Open risers are not permitted.	\$ 675.00	5	Medium		
Building	10	EA Harrold Elementary School	86	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	87	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	88	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	92	There is no accessible route to the basketball court.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	97	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	10	EA Harrold Elementary School	98	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	99	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	102	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	105	The accessible route contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	106	The stairway only has a handrail on one side.	\$ 1,012.50	5	Medium		
Building	10	EA Harrold Elementary School	107	There is no assisted listening system in the assembly area.	\$ 3,375.00	5	Medium		
Building	10	Millington Elementary School	109	The door lock is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	113	The walking surface is obstructed. A 36 inch minimum clear walking surface is required.	\$ 33.75	5	Medium		
Building	10	EA Harrold Elementary School	119	The walking surface is obstructed. A 36 inch minimum clear walking surface is required.	\$ 33.75	5	Medium		
Building	10	EA Harrold Elementary School	135	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	139	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	140	Compliant turning space has not been provided.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	141	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	143	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	144	Compliant turning space has not been provided.	\$ 2,025.00	5	Medium		
Building	10	EA Harrold Elementary School	175	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	10	EA Harrold Elementary School	176	The threshold has a vertical change greater than 1/4 inch high.	\$ 675.00	5	Medium		
Building	10	EA Harrold Elementary School	178	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	10	EA Harrold Elementary School	179	The threshold has a vertical change greater than 1/4 inch high.	\$ 675.00	5	Medium		
Building	10	EA Harrold Elementary School	186	The maneuvering clearance on the approach side is long enough.	\$ -	5	Medium		
Building	10	EA Harrold Elementary School	192	The maneuvering clearance at the door is obstructed.	\$ -	5	Medium		
Building	10	EA Harrold Elementary School	193	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	10	EA Harrold Elementary School	205	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	209	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	211	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	214	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	217	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	222	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	225	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	228	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	EA Harrold Elementary School	232	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	235	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	EA Harrold Elementary School	238	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	10	Millington Elementary School	241	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ -	5	Medium		
Building	10	EA Harrold Elementary School	253	The threshold has a vertical change greater than 1/4 inch high.	\$ 675.00	5	Medium		
Building	11	Millington Middle School	6	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	11	Millington Middle School	7	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	14	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	11	Millington Middle School	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	21	Stairways must have handrails on both sides.	\$ 2,025.00	5	Medium		
Building	11	Millington Middle School	58	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	11	Millington Middle School	75	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	76	The door exceeds the maximum pressure to open the door.	\$ 135.00	5	Medium		
Building	11	Millington Middle School	78	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	79	The door exceeds the maximum pressure to open the door.	\$ 135.00	5	Medium		
Building	11	Millington Middle School	93	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	11	Millington Middle School	94	There are no accessible work surfaces.	\$ 2,025.00	5	Medium		
Building	11	Millington Middle School	138	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	140	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	141	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	142	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	143	The door recessed greater than 8 inches deep with non-compliant latch side clearance.	\$ 3,375.00	5	Medium		
Building	11	Millington Middle School	148	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	149	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	150	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	152	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	154	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	155	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	156	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	157	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	160	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	161	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	162	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	163	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ -	5	Medium		
Building	11	Millington Middle School	167	The door/gate operating hardware is not accessible.	\$ 4,556.25	5	Medium		
Building	11	Millington Middle School	168	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ -	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	11	Millington Middle School	169	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ -	5	Medium		
Building	11	Millington Middle School	187	The door recessed greater than 8 inches deep with non-compliant latch side clearance.	\$ 3,375.00	5	Medium		
Building	11	Millington Middle School	193	The door recessed greater than 8 inches deep with non-compliant latch side clearance.	\$ 3,375.00	5	Medium		
Building	11	Millington Middle School	194	There is a change in level greater than 1/4 inch.	\$ 270.00	5	Medium		
Building	11	Millington Middle School	204	Compliant room identification signs are missing.	\$ 303.75	5	Medium		
Building	11	Millington Middle School	221	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	222	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	223	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	11	Millington Middle School	229	The landing at the change of direction is not the correct size.	\$ 2,025.00	5	Medium		
Building	11	Millington Middle School	231	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	12	Millington Central High School	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	12	The landing at the entrance doors exceeds 2% slope.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	17	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	18	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	19	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	20	The landing at the entrance doors exceeds 2% slope.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	22	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	29	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	30	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	32	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	33	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	35	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	36	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	37	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	39	The surface of the curb ramp is not firm, stable and/or slip resistant..	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	41	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	51	The ramp run has not been provided with edge protection.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	52	The ramp does not have compliant handrails.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	53	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	54	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	60	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	68	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	70	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	77	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	12	Millington Central High School	84	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 2,700.00	5	Medium		
Building	12	Millington Central High School	88	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	12	Millington Central High School	94	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	12	Millington Central High School	96	The transaction counter is too high.	\$ 2,700.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	98	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	115	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 270.00	5	Medium		
Building	12	Millington Central High School	118	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration, addition or construction of existing facilities which predate The Americans with Disabilities Act.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	119	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration, addition or construction of existing facilities which predate The Americans with Disabilities Act.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	123	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration, addition or construction of existing facilities which predate The Americans with Disabilities Act.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	124	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration, addition or construction of existing facilities which predate The Americans with Disabilities Act.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	126	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration, addition or construction of existing facilities which predate The Americans with Disabilities Act.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	127	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration, addition or construction of existing facilities which predate The Americans with Disabilities Act.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	207	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	211	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	212	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	213	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	218	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	220	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	224	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	245	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	246	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	247	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	253	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	254	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	255	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	264	There are no accessible work surfaces.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	266	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	5	Medium		
Building	12	Millington Central High School	269	The door recessed greater than 8 inches deep with non-compliant latch side clearance.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	270	There are no accessible work surfaces.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	281	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	283	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	291	The controls are located such that operation require reaching across burners.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	298	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	300	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	301	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	303	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	308	The room contains 6 or more fixtures and therefore must have a minimum of one ambulatory toilet stall.	\$ 4,050.00	5	Medium		
Building	12	Millington Central High School	325	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	326	The threshold has a vertical change greater than 1/4 inch high.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	329	There is no accessible route to the stadium seating.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	331	Wheelchair spaces shall be provided in assembly areas with fixed seating.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	333	The 30 inches minimum by 48 inches minimum clear floor space required at the ticket booth is not flat (2% or 1:48 maximum slope) in all directions.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	334	There is no accessible route to the visitor's seating.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	338	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	339	There is no accessible route to the visitor concession stand.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	340	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	344	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	12	Millington Central High School	349	The threshold has a vertical change greater than 1/4 inch high.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	358	The threshold is greater than 1/2 inch high.	\$ 675.00	5	Medium		
Building	12	Millington Central High School	361	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Building	12	Millington Central High School	374	The landing on the push side of the door exceeds 2%.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	381	The maneuvering clearance at the door exceeds 2% slope.	\$ 1,350.00	5	Medium		
Building	12	Millington Central High School	395	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	12	Millington Central High School	400	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	12	Millington Central High School	405	There is no accessible route to the concession stand.	\$ 4,050.00	5	Medium		
Building	12	Millington Central High School	406	The staircase extends down too close to the route of travel.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	407	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	408	The staircase extends down too close to the route of travel.	\$ 2,025.00	5	Medium		
Building	12	Millington Central High School	409	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	410	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	411	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	412	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	422	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	12	Millington Central High School	432	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Building	13	Millington-Memphis Airport	6	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Building	13	Millington-Memphis Airport	17	The threshold is greater than 1/2 inch high.	\$ 675.00	5	Medium		
Building	13	Millington-Memphis Airport	18	The restroom is not nearly compliant.	\$ 10,125.00	5	Medium		
Building	13	Millington-Memphis Airport	19	The door/gate operating hardware is not accessible.	\$ 1,012.50	5	Medium		
Building	13	Millington-Memphis Airport	20	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 2,700.00	5	Medium		
Building	13	Millington-Memphis Airport	21	The landing on the pull side of the doors does not extend far enough on the latch side.	\$ 3,375.00	5	Medium		
Building	1	County Clerk Office/Fire Station #1	12	The restroom is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	1	County Clerk Office/Fire Station #1	46	Knee and toe space has not been provided at the sink.	\$ 3,375.00	6	Medium		
Building	1	County Clerk Office/Fire Station #1	47	The top of the sink is too high.	\$ -	6	Medium		
Building	2	Police Station - Jail - Courts	1	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	2	Police Station - Jail - Courts	2	The van stall is missing a sign identifying it as a van accessible stall.	\$ 270.00	6	Medium		
Building	2	Police Station - Jail - Courts	3	The access aisle is missing at the accessible parking stall.	\$ 2,025.00	6	Medium		
Building	2	Police Station - Jail - Courts	4	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025.00	6	Medium		
Building	2	Police Station - Jail - Courts	5	The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 2,025.00	6	Medium		
Building	2	Police Station - Jail - Courts	6	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 1,350.00	6	Medium		
Building	2	Police Station - Jail - Courts	8	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%.	\$ 3,375.00	6	Medium		
Building	2	Police Station - Jail - Courts	9	The accessible path of travel contains cross slopes greater than 2%.	\$ 3,375.00	6	Medium		
Building	2	Police Station - Jail - Courts	15	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	2	Police Station - Jail - Courts	19	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	2	Police Station - Jail - Courts	25	The restroom is not nearly compliant.	\$ 10,125.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	2	Police Station - Jail - Courts	31	The restroom is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	2	Police Station - Jail - Courts	32	The maneuvering space between the two doors in the vestibule is noncompliant.	\$ 1,350.00	6	Medium		
Building	2	Police Station - Jail - Courts	34	There are no accessible dining surfaces.	\$ 2,025.00	6	Medium		
Building	2	Police Station - Jail - Courts	35	There are not enough accessible cell for this facility.	\$ 16,200.00	6	Medium		
Building	2	Police Station - Jail - Courts	37	The grab bar opposite the seat does not extend far enough along the back wall.	\$ 1,012.50	6	Medium		
Building	2	Police Station - Jail - Courts	39	There are no accessible dining surfaces.	\$ 2,025.00	6	Medium		
Building	2	Police Station - Jail - Courts	40	There are not enough accessible cell for this facility.	\$ 16,200.00	6	Medium		
Building	2	Police Station - Jail - Courts	42	The grab bar opposite the seat does not extend far enough along the back wall.	\$ 1,012.50	6	Medium		
Building	2	Police Station - Jail - Courts	44	The restroom is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	2	Police Station - Jail - Courts	46	There are not enough accessible cell for this facility.	\$ 16,200.00	6	Medium		
Building	2	Police Station - Jail - Courts	49	The restroom is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	2	Police Station - Jail - Courts	60	The restrooms is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	2	Police Station - Jail - Courts	61	There are no accessible bathing or shower facilities.	\$ 6,750.00	6	Medium		
Building	2	Police Station - Jail - Courts	69	There are no accessible bathing or shower facilities.	\$ 6,750.00	6	Medium		
Building	2	Police Station - Jail - Courts	70	The restrooms is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	2	Police Station - Jail - Courts	81	The restroom is not nearly compliant.	\$ 13,500.00	6	Medium		
Building	2	Police Station - Jail - Courts	83	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	2	Police Station - Jail - Courts	84	Knee and toe space has not been provided at the sink.	\$ -	6	Medium		
Building	2	Police Station - Jail - Courts	85	There is no accessible route to the (judge seat or court clerk seat)	\$ 4,725.00	6	Medium		
Building	2	Police Station - Jail - Courts	92	The kitchen counter top is too high.	\$ 3,375.00	6	Medium		
Building	2	Police Station - Jail - Courts	93	Knee and toe space has not been provided at the sink.	\$ -	6	Medium		
Building	2	Police Station - Jail - Courts	94	The restroom is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	2	Police Station - Jail - Courts	100	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	2	Police Station - Jail - Courts	101	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	2	Police Station - Jail - Courts	105	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 3,375.00	6	Medium		
Building	2	Police Station - Jail - Courts	111	The restroom is not nearly compliant.	\$ 10,125.00	6	Medium		
Building	2	Police Station - Jail - Courts	112	The ramp run has not been provided with edge protection.	\$ 3,375.00	6	Medium		
Building	2	Police Station - Jail - Courts	113	The ramp does not have compliant handrails.	\$ 3,375.00	6	Medium		
Building	2	Police Station - Jail - Courts	114	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 4,725.00	6	Medium		
Building	3	Millington Public Library	1	The landing at the entrance door exceeds 2% slope.	\$ 3,375.00	6	Medium		
Building	3	Millington Public Library	5	The wall sign is incorrectly located.	\$ 202.50	6	Medium		
Building	3	Millington Public Library	8	The clear floor space around the toilet is obstructed by the (urinal).	\$ 3,375.00	6	Medium		
Building	3	Millington Public Library	10	The wall sign is incorrectly located.	\$ 202.50	6	Medium		
Building	3	Millington Public Library	13	The clear floor space around the toilet is obstructed by the (XX).	\$ 3,375.00	6	Medium		
Building	3	Millington Public Library	18	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 4,050.00	6	Medium		
Building	3	Millington Public Library	19	The restroom is not nearly compliant.	\$ 13,500.00	6	Medium		
Building	3	Millington Public Library	20	The kitchen counter top is too high.	\$ 3,375.00	6	Medium		
Building	3	Millington Public Library	21	Knee and toe space has not been provided at the sink.	\$ -	6	Medium		
Building	3	Millington Public Library	26	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 2,025.00	6	Medium		
Building	3	Millington Public Library	27	The kitchen counter top is too high.	\$ 3,375.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	3	Millington Public Library	28	Knee and toe space has not been provided at the sink.	\$ -	6	Medium		
Building	3	Millington Public Library	31	The counter is too high.	\$ 2,025.00	6	Medium		
Building	4	City Hall	14	Compliant room identification signs are missing.	\$ 202.50	6	Medium		
Building	4	City Hall	19	The clear floor space between the lavatory and the toilet is too narrow.	\$ 3,375.00	6	Medium		
Building	4	City Hall	24	Compliant room identification signs are missing.	\$ 202.50	6	Medium		
Building	4	City Hall	29	The clear floor space between the lavatory and the toilet is too narrow.	\$ 3,375.00	6	Medium		
Building	4	City Hall	42	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 2,025.00	6	Medium		
Building	4	City Hall	43	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 6,075.00	6	Medium		
Building	4	City Hall	47	Knee and toe space has not been provided at the sink.	\$ 3,375.00	6	Medium		
Building	4	City Hall	48	The top of the sink is too high.	\$ -	6	Medium		
Building	4	City Hall	50	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 2,025.00	6	Medium		
Building	4	City Hall	51	The maneuvering clearance at the door is obstructed.	\$ 2,025.00	6	Medium		
Building	5	Public Works	20	The restroom is not nearly compliant. The restroom does not have the required minimum clear floor space or maneuvering clearances for the toilet. The restroom does not have the required minimum clear floor space or maneuvering clearances for the lava	\$ 13,500.00	6	Medium		
Building	5	Public Works	21	The restroom is not nearly compliant. The restroom does not have the required minimum clear floor space or maneuvering clearances for the toilet. The restroom does not have the required minimum clear floor space or maneuvering clearances for the lava	\$ 13,500.00	6	Medium		
Building	6	Baker Community Center	1	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	6	Baker Community Center	4	The accessible route between the building entrance and the accessible parking on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 540.00	6	Medium		
Building	6	Baker Community Center	5	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Building	6	Baker Community Center	6	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	6	Baker Community Center	7	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Building	6	Baker Community Center	8	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Building	6	Baker Community Center	9	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	6	Baker Community Center	10	The accessible route between the building entrance and the accessible parking on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 540.00	6	Medium		
Building	6	Baker Community Center	11	The accessible route between the building entrance and the accessible parking on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 540.00	6	Medium		
Building	6	Baker Community Center	19	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	6	Baker Community Center	20	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,012.50	6	Medium		
Building	6	Baker Community Center	23	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	29	Knee and toe clearance has not been provided at the sink.	\$ 3,375.00	6	Medium		
Building	6	Baker Community Center	30	Knee and toe clearance has not been provided at the sink.	\$ -	6	Medium		
Building	6	Baker Community Center	32	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	34	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	6	Baker Community Center	41	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	42	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	45	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	48	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	51	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	53	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	57	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 4,050.00	6	Medium		
Building	6	Baker Community Center	67	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	6	Baker Community Center	71	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 4,050.00	6	Medium		
Building	7	USA Stadium Complex	1	The required parking signage is missing.	\$ 270.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	7	USA Stadium Complex	2	The required parking signage is missing.	\$ 270.00	6	Medium		
Building	7	USA Stadium Complex	3	The required parking signage is missing.	\$ 270.00	6	Medium		
Building	7	USA Stadium Complex	4	The required parking signage is missing.	\$ 270.00	6	Medium		
Building	7	USA Stadium Complex	5	The required parking signage is missing.	\$ 270.00	6	Medium		
Building	7	USA Stadium Complex	6	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	7	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	8	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	9	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	10	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	11	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	12	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	13	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	7	USA Stadium Complex	14	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 1,350.00	6	Medium		
Building	7	USA Stadium Complex	15	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	16	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	17	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	18	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	19	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	20	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	21	The vegetation extends down too close to the route of travel.	\$ 135.00	6	Medium		
Building	7	USA Stadium Complex	22	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	23	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	7	USA Stadium Complex	24	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	25	The tree branch projects more than 4 inches into the circulation path.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	26	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	27	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	28	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	29	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	30	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	31	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	32	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 540.00	6	Medium		
Building	7	USA Stadium Complex	33	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	34	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Building	7	USA Stadium Complex	35	There is no accessible route to the picnic tables.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	36	There is no accessible route to the bench.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	37	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	38	There is no accessible route to the field, benches, and trash receptacle.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	43	Stairways must have handrails on both sides.	\$ 1,012.50	6	Medium		
Building	7	USA Stadium Complex	45	The stairway only has a handrail on one side.	\$ 1,012.50	6	Medium		
Building	7	USA Stadium Complex	46	Open risers are not permitted.	\$ 1,687.50	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	7	USA Stadium Complex	47	Open risers are not permitted.	\$ 1,687.50	6	Medium		
Building	7	USA Stadium Complex	48	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,012.50	6	Medium		
Building	7	USA Stadium Complex	53	Open risers are not permitted.	\$ 1,687.50	6	Medium		
Building	7	USA Stadium Complex	54	The handrails as well as the handrail extensions are not at the correct height.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	55	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ -	6	Medium		
Building	7	USA Stadium Complex	56	Open risers are not permitted.	\$ 1,687.50	6	Medium		
Building	7	USA Stadium Complex	57	The handrails as well as the handrail extensions are not at the correct height.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	58	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ -	6	Medium		
Building	7	USA Stadium Complex	59	Open risers are not permitted.	\$ 1,687.50	6	Medium		
Building	7	USA Stadium Complex	60	The handrails as well as the handrail extensions are not at the correct height.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	61	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ -	6	Medium		
Building	7	USA Stadium Complex	63	Open risers are not permitted.	\$ 1,687.50	6	Medium		
Building	7	USA Stadium Complex	64	The handrails as well as the handrail extensions are not at the correct height.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	65	Open risers are not permitted.	\$ 1,687.50	6	Medium		
Building	7	USA Stadium Complex	66	The handrails as well as the handrail extensions are not at the correct height.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	67	The handrails as well as the handrail extensions are not at the correct height.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	68	Compliant room identification signs are missing on the strike side of the door.	\$ 303.75	6	Medium		
Building	7	USA Stadium Complex	75	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	7	USA Stadium Complex	77	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	7	USA Stadium Complex	78	Compliant room identification signs are missing on the strike side of the door.	\$ 303.75	6	Medium		
Building	7	USA Stadium Complex	83	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	7	USA Stadium Complex	92	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	7	USA Stadium Complex	96	The knee clearance not compliant.	\$ 3,375.00	6	Medium		
Building	7	USA Stadium Complex	98	There are no accessible bathing or shower facilities.	\$ 3,375.00	6	Medium		
Building	7	USA Stadium Complex	99	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	7	USA Stadium Complex	100	The knee clearance not compliant.	\$ 3,375.00	6	Medium		
Building	7	USA Stadium Complex	103	There are no accessible bathing or shower facilities.	\$ 3,375.00	6	Medium		
Building	7	USA Stadium Complex	104	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	7	USA Stadium Complex	111	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	7	USA Stadium Complex	113	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	7	USA Stadium Complex	120	The walking surface is obstructed. A 36 inch minimum clear walking surface is required.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	121	Compliant room identification signs are missing on the strike side of the door.	\$ 303.75	6	Medium		
Building	7	USA Stadium Complex	123	The ramp run has not been provided with edge protection.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	124	The ramp does not have compliant handrails.	\$ -	6	Medium		
Building	7	USA Stadium Complex	131	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	7	USA Stadium Complex	132	The walking surface is obstructed. A 36 inch minimum clear walking surface is required.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	133	Compliant room identification signs are missing on the strike side of the door.	\$ 303.75	6	Medium		
Building	7	USA Stadium Complex	135	The ramp run has not been provided with edge protection.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	136	The ramp does not have compliant handrails.	\$ -	6	Medium		
Building	7	USA Stadium Complex	138	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	7	USA Stadium Complex	139	There is no accessible route to the field.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	140	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Building	7	USA Stadium Complex	141	There is no accessible route to the field.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	142	There is no accessible route to the bullpen.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	143	There is no accessible route to the bleachers.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	144	There is no accessible route to the press box.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	145	Open risers are not permitted.	\$ 1,687.50	6	Medium		
Building	7	USA Stadium Complex	146	The stairway only has a handrail on one side.	\$ 2,025.00	6	Medium		
Building	7	USA Stadium Complex	147	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ -	6	Medium		
Building	7	USA Stadium Complex	150	The handrail does not extend past the ramp.	\$ 1,012.50	6	Medium		
Building	8	Millington Gym	12	The wall sign is incorrectly located.	\$ 168.75	6	Medium		
Building	8	Millington Gym	13	There are no accessible bathing and shower facilities.	\$ 5,400.00	6	Medium		
Building	8	Millington Gym	17	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	8	Millington Gym	20	The wall sign is incorrectly located.	\$ 168.75	6	Medium		
Building	8	Millington Gym	21	There are no accessible bathing and shower facilities.	\$ 5,400.00	6	Medium		
Building	8	Millington Gym	25	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	8	Millington Gym	36	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	8	Millington Gym	47	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	1	There are no van accessible parking stalls.	\$ 270.00	6	Medium		
Building	10	EA Harrold Elementary School	4	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	10	EA Harrold Elementary School	5	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	7	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 202.50	6	Medium		
Building	10	EA Harrold Elementary School	8	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675.00	6	Medium		
Building	10	EA Harrold Elementary School	9	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	11	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	13	There is no accessible route to the play equipment.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	14	There is no accessible route to the garden.	\$ 2,025.00	6	Medium		
Building	10	Millington Elementary School	15	There is no accessible route to the play equipment.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	16	There is no accessible route to the play equipment.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	17	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 2,025.00	6	Medium		
Building	10	Millington Elementary School	19	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	21	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	22	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	24	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	25	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	26	There is no accessible route to the play equipment.	\$ 675.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	EA Harrold Elementary School	27	The ground or deck surface does not extend 12 inches minimum.	\$ 2,025.00	6	Medium		
Building	10	EA Harrold Elementary School	28	The vegetation extends down too close to the route of travel.	\$ 135.00	6	Medium		
Building	10	Millington Elementary School	29	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	31	There is no accessible route to the play equipment.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	33	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	35	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	36	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	37	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	38	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	39	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	41	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	42	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	43	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	44	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	45	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	46	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	48	The transfer platform is not level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	50	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	51	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Building	10	Millington Elementary School	53	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	54	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	60	There is no accessible route to the play equipment.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	61	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	62	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	63	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	65	The stairway only has a handrail on one side.	\$ 1,012.50	6	Medium		
Building	10	Millington Elementary School	66	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	67	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	Millington Elementary School	72	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	74	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	77	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	79	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	80	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	Millington Elementary School	86	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	Millington Elementary School	91	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	92	The wall sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	95	The accessible route of travel contains cross slopes greater than 2%.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	96	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	98	The wall sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	100	The cabinet projects more than 4 inches into the circulation path.	\$ 675.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	Millington Elementary School	101	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	EA Harrold Elementary School	103	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	103	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	104	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	104	The kitchen counter top is too high.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	107	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration, addition or construction of existing facilities which predate The Americans with Disabilities Act.	\$ -	6	Medium		
Building	10	EA Harrold Elementary School	108	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	108	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	110	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	EA Harrold Elementary School	112	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	10	EA Harrold Elementary School	114	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	114	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	118	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	10	EA Harrold Elementary School	120	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	121	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	123	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	EA Harrold Elementary School	124	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	10	EA Harrold Elementary School	126	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	6	Medium		
Building	10	Millington Elementary School	127	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	128	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	131	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	135	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	137	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	138	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	139	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	141	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	143	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	145	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	145	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	147	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	149	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	151	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	153	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	155	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	156	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	157	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	159	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	160	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	10	Millington Elementary School	160	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	161	Compliant room identification signs are missing.	\$ 168.75	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	EA Harrold Elementary School	163	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	10	Millington Elementary School	163	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	164	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	166	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	168	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	169	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	10	Millington Elementary School	169	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	Millington Elementary School	171	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	172	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	173	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	174	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	175	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	177	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	177	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	179	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	180	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	10	EA Harrold Elementary School	181	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	181	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	182	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	EA Harrold Elementary School	183	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	183	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	184	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	185	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	185	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	186	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	188	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	188	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	190	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	190	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	191	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	192	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	194	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	194	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	195	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	196	The kitchen counter top is too high.	\$ 2,025.00	6	Medium		
Building	10	Millington Elementary School	196	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	198	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	EA Harrold Elementary School	199	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	200	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	201	Compliant room identification signs are missing.	\$ 303.75	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	Millington Elementary School	201	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	202	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	Millington Elementary School	202	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	EA Harrold Elementary School	203	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	204	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	204	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	206	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	Millington Elementary School	206	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	EA Harrold Elementary School	207	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	EA Harrold Elementary School	208	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	208	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	210	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	Millington Elementary School	211	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	212	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	212	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	213	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	213	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	214	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	215	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	EA Harrold Elementary School	216	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	216	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	218	The shelves projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	Millington Elementary School	218	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	219	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	219	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	6	Medium		
Building	10	EA Harrold Elementary School	221	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	222	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	223	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	Millington Elementary School	223	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	224	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	225	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	226	The shelves projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	EA Harrold Elementary School	227	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	227	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	228	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	229	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	Millington Elementary School	230	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	231	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	231	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	233	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	Millington Elementary School	233	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	EA Harrold Elementary School	234	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	236	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	Millington Elementary School	236	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	237	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	238	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	10	EA Harrold Elementary School	239	The shelf projects more than 4 inches into the circulation path.	\$ 607.50	6	Medium		
Building	10	EA Harrold Elementary School	240	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	241	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	10	EA Harrold Elementary School	242	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	242	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	243	The shelves projects more than 4 inches into the circulation path.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	243	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	244	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	10	EA Harrold Elementary School	245	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	245	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	247	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	10	Millington Elementary School	247	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	248	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	249	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	10	Millington Elementary School	249	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	250	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	EA Harrold Elementary School	251	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	10	Millington Elementary School	251	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	252	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	10	Millington Elementary School	253	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	EA Harrold Elementary School	254	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	10	Millington Elementary School	255	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	257	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	259	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	260	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	261	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	263	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	264	Compliant room identification signs are missing.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	265	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	268	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	269	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	272	The accessible route of travel contains cross slopes greater than 2%.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	273	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	275	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	Millington Elementary School	278	The accessible route of travel contains cross slopes greater than 2%.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	279	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	281	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	284	The accessible route of travel contains cross slopes greater than 2%.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	285	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	287	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	290	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	292	The accessible route of travel contains cross slopes greater than 2%.	\$ 675.00	6	Medium		
Building	10	Millington Elementary School	293	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	10	Millington Elementary School	296	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Building	10	Millington Elementary School	298	The accessible route of travel contains cross slopes greater than 2%.	\$ 675.00	6	Medium		
Building	11	Millington Middle School	4	The required parking signage is missing.	\$ 270.00	6	Medium		
Building	11	Millington Middle School	5	The required parking signage is missing.	\$ 270.00	6	Medium		
Building	11	Millington Middle School	57	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	60	The drop box projects more than 4 inches into the circulation path.	\$ 270.00	6	Medium		
Building	11	Millington Middle School	61	The drop box projects more than 4 inches into the circulation path.	\$ 270.00	6	Medium		
Building	11	Millington Middle School	62	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	65	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	66	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	68	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	69	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	71	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	73	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	85	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	11	Millington Middle School	92	Compliant room identification signs are missing.	\$ 607.50	6	Medium		
Building	11	Millington Middle School	95	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	98	The top of the sink is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	102	The top of the sink is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	106	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	110	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	111	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	112	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	113	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	114	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	115	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	116	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	117	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	118	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	119	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	120	Compliant room identification signs are missing.	\$ 303.75	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	11	Millington Middle School	121	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	122	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	123	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	124	The counter top is too high.	\$ 2,025.00	6	Medium		
Building	11	Millington Middle School	127	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	128	The knee clearance not compliant.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	130	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	131	The counter top is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	132	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	133	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	135	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	136	The counter top is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	137	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	139	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	6	Medium		
Building	11	Millington Middle School	144	The restroom is not nearly compliant.	\$ 405.00	6	Medium		
Building	11	Millington Middle School	153	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	158	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	164	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	166	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	170	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	171	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	172	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	173	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	174	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	175	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	176	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	177	The counter top is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	178	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	179	The sink and counter top is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	180	The restroom is not nearly compliant.	\$ 6,075.00	6	Medium		
Building	11	Millington Middle School	182	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	183	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	186	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	188	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	189	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	192	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	195	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	196	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	197	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	198	Compliant room identification signs are missing.	\$ 303.75	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	11	Millington Middle School	199	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	200	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	201	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	202	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	203	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	205	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	206	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	207	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	208	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	209	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	210	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	212	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	213	The counter top is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	214	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Building	11	Millington Middle School	216	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	11	Millington Middle School	217	The counter top is too high.	\$ 2,700.00	6	Medium		
Building	11	Millington Middle School	218	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	11	Millington Middle School	225	The handrail extension is not a minimum 12 inches.	\$ 1,012.50	6	Medium		
Building	11	Millington Middle School	228	The ramp does not have compliant handrails.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	4	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	12	Millington Central High School	5	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Building	12	Millington Central High School	8	The required parking signage is missing.	\$ 1,620.00	6	Medium		
Building	12	Millington Central High School	14	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	15	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	25	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	26	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	6	Medium		
Building	12	Millington Central High School	27	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675.00	6	Medium		
Building	12	Millington Central High School	28	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	34	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	38	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	50	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 270.00	6	Medium		
Building	12	Millington Central High School	55	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	57	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	63	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 675.00	6	Medium		
Building	12	Millington Central High School	66	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	71	The ramp run has not been provided with edge protection.	\$ 675.00	6	Medium		
Building	12	Millington Central High School	72	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	73	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	74	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	76	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	78	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	83	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	95	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	99	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	100	The counter top is too high.	\$ 3,375.00	6	Medium		
Building	12	Millington Central High School	102	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	103	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	104	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	105	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	106	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	107	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	108	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	109	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	110	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	111	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	112	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	113	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	116	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	132	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	133	The counter is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	135	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	136	The counter is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	139	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	151	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	152	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	153	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	154	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	155	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	156	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	157	Compliant room identification signs are missing.	\$ 607.50	6	Medium		
Building	12	Millington Central High School	158	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	160	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	162	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	164	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	175	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	192	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	193	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	194	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	195	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	196	Compliant room identification signs are missing.	\$ 303.75	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	197	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	198	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	199	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	200	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	201	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	202	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	203	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	204	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	205	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	206	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	208	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	214	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than	\$ 675.00	6	Medium		
Building	12	Millington Central High School	221	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	223	The tactile sign is incorrectly located.	\$ 135.00	6	Medium		
Building	12	Millington Central High School	225	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	226	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	227	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	228	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	229	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	230	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	231	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	232	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	233	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	234	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	235	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	236	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	237	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	238	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	240	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	242	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	248	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	256	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than	\$ 2,025.00	6	Medium		
Building	12	Millington Central High School	258	The tactile sign is incorrectly located.	\$ 135.00	6	Medium		
Building	12	Millington Central High School	259	The restroom is not nearly compliant.	\$ 13,500.00	6	Medium		
Building	12	Millington Central High School	260	The tactile sign is incorrectly located.	\$ 135.00	6	Medium		
Building	12	Millington Central High School	261	The restroom is not nearly compliant.	\$ 13,500.00	6	Medium		
Building	12	Millington Central High School	267	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	271	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	273	Knee and toe space has not been provided at the sink.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	275	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	276	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	277	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	278	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	279	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	280	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	282	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	284	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	285	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	286	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	287	The restroom is not nearly compliant.	\$ 14,850.00	6	Medium		
Building	12	Millington Central High School	288	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	289	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	292	Knee and toe space has not been provided at the sink.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	293	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	294	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	296	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	297	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	299	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	302	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	304	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	305	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	306	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	307	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	309	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Building	12	Millington Central High School	312	The room contains 6 or more fixtures and therefore must have a minimum of one ambulatory toilet stall.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	313	The tactile sign is incorrectly located.	\$ 135.00	6	Medium		
Building	12	Millington Central High School	316	The speaker projects more than 4 inches into the circulation path.	\$ 675.00	6	Medium		
Building	12	Millington Central High School	317	The speaker projects more than 4 inches into the circulation path.	\$ 675.00	6	Medium		
Building	12	Millington Central High School	318	The tactile sign is incorrectly located.	\$ 135.00	6	Medium		
Building	12	Millington Central High School	327	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	328	The restrooms is not nearly compliant.	\$ 6,075.00	6	Medium		
Building	12	Millington Central High School	354	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	357	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	359	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	363	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	365	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	367	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	371	Accessible toilets must have grab bars installed.	\$ 1,080.00	6	Medium		
Building	12	Millington Central High School	375	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	380	Accessible toilets must have grab bars installed.	\$ 1,080.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	382	The kitchen counter top is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	390	The restrooms is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	392	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	393	The handrail does not have the required extension at the top of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	394	The handrail does not have the required extension at the top of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	396	The top of the sink is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	397	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 202.50	6	Medium		
Building	12	Millington Central High School	398	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	401	The top of the sink is too high.	\$ 2,700.00	6	Medium		
Building	12	Millington Central High School	402	The faucet controls requires tight grasping, tight pinching or twisting of the wrist to operate.	\$ 202.50	6	Medium		
Building	12	Millington Central High School	403	The handrail does not have the required extension at the top of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	404	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	413	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	414	The handrail does not have the required extension at the top of the stair flight.	\$ 1,012.50	6	Medium		
Building	12	Millington Central High School	415	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	419	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	421	Compliant room identification signs are missing.	\$ 303.75	6	Medium		
Building	12	Millington Central High School	425	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	427	The restroom is not nearly compliant.	\$ 4,050.00	6	Medium		
Building	12	Millington Central High School	428	There are no accessible bathing or shower facilities.	\$ 3,375.00	6	Medium		
Building	12	Millington Central High School	430	There are no accessible bathing or shower facilities.	\$ 3,375.00	6	Medium		
Building	13	Millington-Memphis Airport	2	The landing at the entrance door exceeds 2% slope.	\$ 3,375.00	6	Medium		
Building	13	Millington-Memphis Airport	4	Knee and toe space has not been provided at the sink.	\$ 3,375.00	6	Medium		
Building	13	Millington-Memphis Airport	5	The kitchen counter top is too high.	\$ -	6	Medium		
Building	13	Millington-Memphis Airport	7	Compliant room identification signs are missing.	\$ 135.00	6	Medium		
Building	13	Millington-Memphis Airport	10	The toilet is not located within the range allowed from the side wall or partition.	\$ 2,025.00	6	Medium		
Building	13	Millington-Memphis Airport	16	Compliant room identification signs are missing.	\$ 135.00	6	Medium		
Building	1	County Clerk Office/Fire Station #1	11	There are not enough drinking fountains.	\$ 3,375.00	7	Medium		
Building	1	County Clerk Office/Fire Station #1	13	The restroom is not nearly compliant.	\$ 10,125.00	7	Medium		
Building	1	County Clerk Office/Fire Station #1	15	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	1	County Clerk Office/Fire Station #1	20	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	1	County Clerk Office/Fire Station #1	32	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	1	County Clerk Office/Fire Station #1	34	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	1	County Clerk Office/Fire Station #1	52	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	12	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	7	Medium		
Building	2	Police Station - Jail - Courts	13	There is no drinking fountain for standing persons.	\$ 4,725.00	7	Medium		
Building	2	Police Station - Jail - Courts	22	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	23	There is no drinking fountain for standing persons.	\$ 4,725.00	7	Medium		
Building	2	Police Station - Jail - Courts	27	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	36	There are not enough drinking fountains.	\$ 4,725.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	2	Police Station - Jail - Courts	45	There are not enough drinking fountains.	\$ 4,725.00	7	Medium		
Building	2	Police Station - Jail - Courts	51	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	2	Police Station - Jail - Courts	54	There are not enough drinking fountains.	\$ 4,725.00	7	Medium		
Building	2	Police Station - Jail - Courts	55	The door must have a smooth surface within 10 inches of the floor on the push side.	\$ 135.00	7	Medium		
Building	2	Police Station - Jail - Courts	56	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	7	Medium		
Building	2	Police Station - Jail - Courts	58	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	62	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	2	Police Station - Jail - Courts	67	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	72	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	2	Police Station - Jail - Courts	78	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 270.00	7	Medium		
Building	2	Police Station - Jail - Courts	80	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	89	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	96	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	98	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	2	Police Station - Jail - Courts	103	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	2	Police Station - Jail - Courts	106	There are not enough drinking fountains.	\$ 4,725.00	7	Medium		
Building	3	Millington Public Library	2	There is no drinking fountain for standing persons.	\$ 4,725.00	7	Medium		
Building	3	Millington Public Library	3	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	7	Medium		
Building	3	Millington Public Library	25	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	4	City Hall	7	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	7	Medium		
Building	4	City Hall	8	There are not enough drinking fountains.	\$ 4,725.00	7	Medium		
Building	4	City Hall	11	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	7	Medium		
Building	4	City Hall	12	The door/gate operating hardware is not accessible.	\$ 337.50	7	Medium		
Building	4	City Hall	15	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	7	Medium		
Building	5	Public Works	15	The vision light panels (glazing/window) are mounted too high.	\$ 1,350.00	7	Medium		
Building	5	Public Works	17	There are not enough drinking fountains.	\$ 4,725.00	7	Medium		
Building	6	Baker Community Center	14	There is no drinking fountain for standing persons.	\$ 5,130.00	7	Medium		
Building	6	Baker Community Center	16	There is no assistive listening system in the assembly area.	\$ 2,025.00	7	Medium		
Building	6	Baker Community Center	21	There is no drinking fountain for standing persons.	\$ 5,130.00	7	Medium		
Building	6	Baker Community Center	25	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	7	Medium		
Building	6	Baker Community Center	28	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	6	Baker Community Center	35	The faucet controls requires tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	6	Baker Community Center	38	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	7	Medium		
Building	6	Baker Community Center	40	The vision light panels (glazing/window) are mounted too high.	\$ 945.00	7	Medium		
Building	6	Baker Community Center	44	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	7	Medium		
Building	6	Baker Community Center	55	The water and drain pipes under the lavatory are not adequately insulated.	\$ 540.00	7	Medium		
Building	6	Baker Community Center	68	The water and drain pipes under the lavatory are not adequately insulated.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	39	The drinking fountain is not accessible.	\$ 2,025.00	7	Medium		
Building	7	USA Stadium Complex	40	There is no drinking fountain for standing persons.	\$ 3,375.00	7	Medium		
Building	7	USA Stadium Complex	41	There are not enough drinking fountains.	\$ 3,375.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	7	USA Stadium Complex	72	The water and drain pipes under the lavatory are not adequately insulated.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	74	The faucet controls are not accessible because they require tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	81	The water and drain pipes under the lavatory are not adequately insulated.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	82	The faucet control is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	93	The dry erase board projects more than 4 inches into the circulation path.	\$ 270.00	7	Medium		
Building	7	USA Stadium Complex	97	The sink is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	101	The sink is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 1,215.00	7	Medium		
Building	7	USA Stadium Complex	107	The water and drain pipes under the lavatory are not adequately insulated.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	108	The sink is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 1,215.00	7	Medium		
Building	7	USA Stadium Complex	109	The water and drain pipes under the lavatory are not adequately insulated.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	117	The water and drain pipes under the lavatory are not adequately insulated.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	118	The sink is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 1,215.00	7	Medium		
Building	7	USA Stadium Complex	126	The water and drain pipes under the lavatory are not adequately insulated.	\$ 405.00	7	Medium		
Building	7	USA Stadium Complex	127	The sink is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 1,215.00	7	Medium		
Building	8	Millington Gym	7	There is no drinking fountain for standing persons.	\$ 5,130.00	7	Medium		
Building	8	Millington Gym	8	The drinking fountain projects more than 4 inches into the circulation path.	\$ 5,130.00	7	Medium		
Building	8	Millington Gym	15	The water and drain pipes under the lavatory are not adequately insulated.	\$ 270.00	7	Medium		
Building	8	Millington Gym	23	The water and drain pipes under the lavatory are not adequately insulated.	\$ 270.00	7	Medium		
Building	8	Millington Gym	28	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	8	Millington Gym	32	The rear grab bar is not a minimum 36 inches in length.	\$ 540.00	7	Medium		
Building	8	Millington Gym	33	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	8	Millington Gym	37	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	8	Millington Gym	41	The rear grab bar is not a minimum 36 inches in length.	\$ 540.00	7	Medium		
Building	8	Millington Gym	42	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	8	Millington Gym	45	The maneuvering space on the pull side of the door or gate does not adequately extend beyond the latch side of the door.	\$ -	7	Medium		
Building	8	Millington Gym	46	The flush handle is located on the wrong side of the toilet.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	30	There is no accessible route to the benches.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	31	There is no accessible route to the benches.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	33	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 540.00	7	Medium		
Building	10	Millington Elementary School	40	The operating mechanism of the flag pole is positioned too high for either a side or front approach.	\$ 337.50	7	Medium		
Building	10	EA Harrold Elementary School	43	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 540.00	7	Medium		
Building	10	EA Harrold Elementary School	46	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	48	There is no accessible route to the picnic tables.	\$ 2,025.00	7	Medium		
Building	10	Millington Elementary School	49	Compliance with ASTM F 1292 for Use Zones has not been determined.	\$ 8,100.00	7	Medium		
Building	10	EA Harrold Elementary School	54	There is no accessible route to the bench.	\$ 2,025.00	7	Medium		
Building	10	Millington Elementary School	55	The trash receptacle is not positioned correctly for either a side or front approach.	\$ 675.00	7	Medium		
Building	10	Millington Elementary School	57	Compliance with ASTM F 1292 for Use Zones has not been determined.	\$ 8,100.00	7	Medium		
Building	10	EA Harrold Elementary School	59	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 540.00	7	Medium		
Building	10	Millington Elementary School	59	Compliance with ASTM F 1292 for Use Zones has not been determined.	\$ 8,100.00	7	Medium		
Building	10	EA Harrold Elementary School	62	There is no accessible route to the trash can.	\$ 108.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	Millington Elementary School	73	The drinking fountain is not accessible.	\$ 5,130.00	7	Medium		
Building	10	Millington Elementary School	75	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	10	EA Harrold Elementary School	77	Open risers are not permitted.	\$ 675.00	7	Medium		
Building	10	EA Harrold Elementary School	78	The handrail gripping diameter is noncompliant.	\$ 675.00	7	Medium		
Building	10	Millington Elementary School	78	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	10	EA Harrold Elementary School	82	The ramp does not have compliant handrails.	\$ 2,025.00	7	Medium		
Building	10	Millington Elementary School	82	The PTA mailbox projects more than 4 inches into the circulation path.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	85	The handrail gripping diameter is noncompliant.	\$ 675.00	7	Medium		
Building	10	Millington Elementary School	85	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	89	There is no accessible route to the picnic table.	\$ 2,025.00	7	Medium		
Building	10	Millington Elementary School	89	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	90	There is no accessible route to the picnic table.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	91	There is no accessible route to the trashcan.	\$ 108.00	7	Medium		
Building	10	EA Harrold Elementary School	93	There is no accessible route to the swings.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	94	There is no accessible route to the field.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	95	The 30 inches minimum by 48 inches minimum clear floor space required at the bench is not flat (2% or 1:48 maximum slope) in all directions.	\$ 540.00	7	Medium		
Building	10	EA Harrold Elementary School	96	The 30 inches minimum by 48 inches minimum clear floor space required at the bench is not flat (2% or 1:48 maximum slope) in all directions.	\$ 540.00	7	Medium		
Building	10	Millington Elementary School	97	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	101	The office is not accessible because there is not adequate clear floor space for an approach.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	102	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	Millington Elementary School	105	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 2,430.00	7	Medium		
Building	10	Millington Elementary School	106	The wall-mounted object projects more than 4 inches into the circulation path.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	109	Compliant knee space has not been provided under the lavatory.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	110	The water and drain pipes under the lavatory are not adequately insulated.	\$ 540.00	7	Medium		
Building	10	EA Harrold Elementary School	111	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 1,620.00	7	Medium		
Building	10	EA Harrold Elementary School	115	Compliant knee space has not been provided under the lavatory.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	116	The water and drain pipes under the lavatory are not adequately insulated.	\$ 540.00	7	Medium		
Building	10	Millington Elementary School	116	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	117	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 1,620.00	7	Medium		
Building	10	Millington Elementary School	119	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	Millington Elementary School	120	The paper towel dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	121	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	10	EA Harrold Elementary School	122	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	10	EA Harrold Elementary School	125	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	10	Millington Elementary School	125	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	10	EA Harrold Elementary School	127	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 2,025.00	7	Medium		
Building	10	EA Harrold Elementary School	129	The drinking fountain is not accessible.	\$ 6,750.00	7	Medium		
Building	10	Millington Elementary School	129	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	130	The drinking fountain is not accessible.	\$ 5,130.00	7	Medium		
Building	10	Millington Elementary School	130	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	EA Harrold Elementary School	131	The drinking fountain is not accessible.	\$ 5,130.00	7	Medium		
Building	10	EA Harrold Elementary School	132	The drinking fountain is not accessible.	\$ 6,750.00	7	Medium		
Building	10	EA Harrold Elementary School	133	The drinking fountain is not accessible.	\$ 6,750.00	7	Medium		
Building	10	Millington Elementary School	133	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	EA Harrold Elementary School	134	The drinking fountain is not accessible.	\$ 6,750.00	7	Medium		
Building	10	Millington Elementary School	134	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	10	Millington Elementary School	136	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	138	The wall-mounted object projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	140	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	142	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	144	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	146	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	148	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	150	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	152	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	154	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	156	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	158	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	159	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	161	The water and drain pipes under the lavatory are not adequately insulated.	\$ 540.00	7	Medium		
Building	10	EA Harrold Elementary School	162	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	162	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	164	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	165	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	7	Medium		
Building	10	Millington Elementary School	165	The storage cannisters project more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	166	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675.00	7	Medium		
Building	10	EA Harrold Elementary School	167	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	167	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	170	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	174	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	176	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	178	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	180	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	182	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	184	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	187	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	187	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	189	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	189	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	191	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	Millington Elementary School	193	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	195	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	197	The toilet is not located within the range allowed from the side wall or partition.	\$ 3,105.00	7	Medium		
Building	10	Millington Elementary School	197	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	198	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	Millington Elementary School	199	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	203	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	205	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	207	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	209	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	210	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	215	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	217	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	220	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	221	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	224	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	226	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	229	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	EA Harrold Elementary School	230	There are no accessible work surfaces.	\$ 2,025.00	7	Medium		
Building	10	Millington Elementary School	232	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	234	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	237	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	239	The faucet controls require tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		
Building	10	Millington Elementary School	244	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	246	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	248	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	250	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	252	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	254	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	256	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	258	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	262	The shelf projects more than 4 inches into the circulation path.	\$ 202.50	7	Medium		
Building	10	Millington Elementary School	274	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	Millington Elementary School	280	The flush handle is located on the wrong side of the toilet.	\$ 2,025.00	7	Medium		
Building	10	Millington Elementary School	286	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	Millington Elementary School	291	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	10	Millington Elementary School	297	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	15	There is no accessible route to the compost bins.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	16	There is no accessible route to the garden.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	17	There is no accessible route to the table.	\$ 2,025.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	11	Millington Middle School	19	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	22	The electrical box projects more than 4 inches into the circulation path.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	33	There is no accessible route to the memorial.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	40	There is no accessible route to the picnic table.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	41	There is no accessible route to the benches.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	42	There is no accessible route to the bench.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	43	There is no accessible route to the bench.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	44	There is no accessible route to the bench.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	45	There is no accessible route to the picnic table and grill.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	46	There is no accessible route to the trash can.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	47	There is no accessible route to the trash can.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	48	There is no accessible route to the bench.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	49	There is no accessible route to the bench.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	50	There is no accessible route to the picnic table.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	51	There is no accessible route to the trash can.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	52	There is no accessible route to the picnic tables.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	53	There is no accessible route to the picnic table.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	54	There is no accessible route to the picnic table.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	55	There is no accessible route to the picnic table.	\$ 2,025.00	7	Medium		
Building	11	Millington Middle School	67	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675.00	7	Medium		
Building	11	Millington Middle School	72	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675.00	7	Medium		
Building	11	Millington Middle School	74	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	77	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	80	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	11	Millington Middle School	81	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 1,350.00	7	Medium		
Building	11	Millington Middle School	84	The handrail projects less than 12 inches beyond the landing at the top of the stairs parallel to the floor or ground.	\$ 1,350.00	7	Medium		
Building	11	Millington Middle School	86	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 1,350.00	7	Medium		
Building	11	Millington Middle School	88	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	11	Millington Middle School	89	The handrail projects less than 12 inches beyond the landing at the top of the stairs parallel to the floor or ground.	\$ 1,350.00	7	Medium		
Building	11	Millington Middle School	90	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 1,350.00	7	Medium		
Building	11	Millington Middle School	99	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	11	Millington Middle School	104	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	11	Millington Middle School	125	The faucet control is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 337.50	7	Medium		
Building	11	Millington Middle School	126	The eye wash station is not positioned correctly for either a side or front approach.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	146	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	11	Millington Middle School	147	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ -	7	Medium		
Building	11	Millington Middle School	151	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	11	Millington Middle School	159	The wall-mounted object projects more than 4 inches into the circulation path.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	165	The faucet control is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	11	Millington Middle School	184	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	11	Millington Middle School	185	The faucet control is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	11	Millington Middle School	190	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	11	Millington Middle School	191	The faucet control is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	11	Millington Middle School	219	The drinking fountain is not accessible.	\$ 5,130.00	7	Medium		
Building	11	Millington Middle School	220	The drinking fountain is not accessible.	\$ 5,130.00	7	Medium		
Building	11	Millington Middle School	224	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	226	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 270.00	7	Medium		
Building	11	Millington Middle School	227	There is no drinking fountain for standing persons.	\$ 5,130.00	7	Medium		
Building	11	Millington Middle School	230	There is no drinking fountain for standing persons.	\$ 5,130.00	7	Medium		
Building	11	Millington Middle School	232	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 270.00	7	Medium		
Building	12	Millington Central High School	46	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	12	Millington Central High School	87	There are no accessible work surfaces.	\$ 1,620.00	7	Medium		
Building	12	Millington Central High School	97	There are no accessible work surfaces.	\$ 1,620.00	7	Medium		
Building	12	Millington Central High School	101	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 810.00	7	Medium		
Building	12	Millington Central High School	114	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	12	Millington Central High School	117	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	12	Millington Central High School	122	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 202.50	7	Medium		
Building	12	Millington Central High School	125	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	129	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	130	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	131	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	141	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	12	Millington Central High School	159	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		
Building	12	Millington Central High School	161	There are no accessible work surfaces.	\$ 2,025.00	7	Medium		
Building	12	Millington Central High School	163	There is no accessible route to the raised platform.	\$ 2,025.00	7	Medium		
Building	12	Millington Central High School	167	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	168	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	169	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	170	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	173	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	174	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	215	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	219	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	7	Medium		
Building	12	Millington Central High School	222	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	239	There are no accessible work surfaces.	\$ 1,350.00	7	Medium		
Building	12	Millington Central High School	241	There are no accessible work surfaces.	\$ 1,350.00	7	Medium		
Building	12	Millington Central High School	249	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	257	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	262	The paper towel dispenser's operation mechanism is too high off the floor. Dispensers must have all operable parts a maximum of 48 inches above the floor.	\$ 270.00	7	Medium		
Building	12	Millington Central High School	268	The faucet controls requires tight grasping, tight pinching or twisting of the wrist to operate.	\$ 405.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	274	The controls are located such that operation require reaching across burners.	\$ 2,025.00	7	Medium		
Building	12	Millington Central High School	310	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 202.50	7	Medium		
Building	12	Millington Central High School	311	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 202.50	7	Medium		
Building	12	Millington Central High School	314	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 202.50	7	Medium		
Building	12	Millington Central High School	320	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 168.75	7	Medium		
Building	12	Millington Central High School	322	The maneuvering clearance on the pull side of the door is not long enough in the direction of travel.	\$ -	7	Medium		
Building	12	Millington Central High School	324	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	12	Millington Central High School	330	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 675.00	7	Medium		
Building	12	Millington Central High School	332	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,350.00	7	Medium		
Building	12	Millington Central High School	335	The controls are located such that operation require reaching across burners.	\$ 2,025.00	7	Medium		
Building	12	Millington Central High School	336	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	12	Millington Central High School	337	The light switches are positioned too high for either a side or front approach.	\$ 810.00	7	Medium		
Building	12	Millington Central High School	342	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	12	Millington Central High School	346	The restrooms is not nearly compliant.	\$ 4,050.00	7	Medium		
Building	12	Millington Central High School	347	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	12	Millington Central High School	348	The light switch is positioned too high for either a side or front approach.	\$ 540.00	7	Medium		
Building	12	Millington Central High School	351	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	355	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	12	Millington Central High School	356	There is a change in level greater than 1/4 inch.	\$ 270.00	7	Medium		
Building	12	Millington Central High School	368	The top rim of the lavatory is too high.	\$ 2,025.00	7	Medium		
Building	12	Millington Central High School	369	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	12	Millington Central High School	373	The flush handle is located on the wrong side of the toilet.	\$ 1,350.00	7	Medium		
Building	12	Millington Central High School	376	The top rim of the lavatory is too high.	\$ 2,025.00	7	Medium		
Building	12	Millington Central High School	377	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	12	Millington Central High School	379	The flush handle is located on the wrong side of the toilet.	\$ 1,350.00	7	Medium		
Building	12	Millington Central High School	384	There are not enough drinking fountains.	\$ 4,050.00	7	Medium		
Building	12	Millington Central High School	385	The water and drain pipes under the lavatory are not adequately insulated.	\$ 270.00	7	Medium		
Building	12	Millington Central High School	386	The top rim of the lavatory is too high.	\$ 2,700.00	7	Medium		
Building	12	Millington Central High School	391	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	12	Millington Central High School	399	There are not enough drinking fountains.	\$ 4,050.00	7	Medium		
Building	12	Millington Central High School	420	The faucet controls are not accessible because they require tight grasping, pinching or twisting of the wrist.	\$ 1,215.00	7	Medium		
Building	12	Millington Central High School	426	The faucet controls are not accessible because they require tight grasping, pinching or twisting of the wrist.	\$ 1,215.00	7	Medium		
Building	12	Millington Central High School	429	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Building	13	Millington-Memphis Airport	3	The work surface is too high. The tops of work surfaces provided for public use or common use shall be 28 inches minimum and 34 inches maximum above the finish floor or ground.	\$ 2,025.00	7	Medium		
Building	13	Millington-Memphis Airport	11	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Building	13	Millington-Memphis Airport	12	The flush handle is located on the wrong side of the toilet.	\$ 2,025.00	7	Medium		
Building	13	Millington-Memphis Airport	15	The faucet controls require twisting of the wrist.	\$ 337.50	7	Medium		
Park	1	Aycock Park	32	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	39	There is no accessible route to the dugout and field.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	40	There is no accessible route to the dugout and field.	\$ 2,025.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	2	Biloxi Fields/Miles Baseball Park	41	There is no accessible route to the dugout and field.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	42	There is no accessible route to the dugout and field.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	46	The transaction counter is too high.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	49	The 30 inches minimum by 48 inches minimum clear floor space required at the concession counter is not flat (2% or 1:48 maximum slope) in all directions.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	66	There is no accessible route to the field.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	68	Based on the number of seats provided in this area (100), there should be a minimum of (4) wheelchair seating spaces.	\$ 675.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	69	Based on the number of seats provided in this area (100), there should be a minimum of (4) wheelchair seating spaces.	\$ 675.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	71	There is no accessible route to the field.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	72	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	73	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	74	The 30 inches minimum by 48 inches minimum clear floor space required at the locker room entrance is not flat (2% or 1:48 maximum slope) in all directions.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	75	The 30 inches minimum by 48 inches minimum clear floor space required at the locker room entrance is not flat (2% or 1:48 maximum slope) in all directions.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	76	The transaction counter is too high.	\$ 2,700.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	81	The 30 inches minimum by 48 inches minimum clear floor space required at the concessions entrance is not flat (2% or 1:48 maximum slope) in all directions.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	83	The maneuvering clearance at the door exceeds 2% slope. Maneuvering clearance must be generally flat with a 2% maximum slope in any direction over the entire clearance surface. The maneuvering clearance must be clear of obstructions.	\$ 2,025.00	5	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	85	The maneuvering clearance at the door exceeds 2% slope. Maneuvering clearance must be generally flat with a 2% maximum slope in any direction over the entire clearance surface. The maneuvering clearance must be clear of obstructions.	\$ 2,025.00	5	Medium		
Park	3	Centennial Park	36	There are no accessible tables.	\$ 1,080.00	5	Medium		
Park	3	Centennial Park	38	The door/gate operating hardware is not accessible.	\$ 506.25	5	Medium		
Park	4	Joyner Fields	1	There is no accessible route to the (concession stand).	\$ 4,725.00	5	Medium		
Park	4	Joyner Fields	2	The transaction counter is too high.	\$ 2,025.00	5	Medium		
Park	4	Joyner Fields	4	The threshold is greater than 1/2 inch high.	\$ 2,025.00	5	Medium		
Park	4	Joyner Fields	6	There is no accessible route to the (restroom-pavillion).	\$ 6,750.00	5	Medium		
Park	4	Joyner Fields	8	The restroom is not nearly compliant.	\$ 13,500.00	5	Medium		
Park	4	Joyner Fields	9	There is no accessible route to the (restroom-pavillion).	\$ -	5	Medium		
Park	4	Joyner Fields	11	The restroom is not nearly compliant.	\$ 13,500.00	5	Medium		
Park	4	Joyner Fields	12	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	5	Medium		
Park	4	Joyner Fields	13	There is no accessible route to the (ball field #1).	\$ 13,500.00	5	Medium		
Park	4	Joyner Fields	14	The wheelchair seating spaces are not on an accessible route. Wheelchair seating spaces shall adjoin accessible routes and shall not overlap circulation paths. Accessible routes shall not overlap wheelchair spaces.	\$ 4,725.00	5	Medium		
Park	4	Joyner Fields	19	There is no accessible route to the (ball field #2).	\$ -	5	Medium		
Park	4	Joyner Fields	20	The wheelchair seating spaces are not on an accessible route. Wheelchair seating spaces shall adjoin accessible routes and shall not overlap circulation paths. Accessible routes shall not overlap wheelchair spaces.	\$ 4,725.00	5	Medium		
Park	4	Joyner Fields	26	The surfaces of the accessible parking spaces and access aisles are not firm, stable, and slip resistant.	\$ 33,750.00	5	Medium		
Park	5	Lions Park Pavillion	10	The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 405.00	5	Medium		
Park	5	Lions Park Pavillion	11	The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 405.00	5	Medium		
Park	5	Lions Park Pavillion	12	The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 405.00	5	Medium		
Park	5	Lions Park Pavillion	13	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Park	5	Lions Park Pavillion	14	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		
Park	5	Lions Park Pavillion	15	The accessible path of travel contains cross slopes greater than 2%.	\$ 2,025.00	5	Medium		
Park	5	Lions Park Pavillion	16	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		
Park	5	Lions Park Pavillion	17	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		
Park	5	Lions Park Pavillion	18	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	5	Lions Park Pavillion	20	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		
Park	5	Lions Park Pavillion	21	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		
Park	5	Lions Park Pavillion	22	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 270.00	5	Medium		
Park	5	Lions Park Pavillion	23	There is no accessible route to the grill.	\$ 2,025.00	5	Medium		
Park	5	Lions Park Pavillion	24	The electrical outlet is positioned too high for either a side or front approach.	\$ 270.00	5	Medium		
Park	6	Oak Park	1	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	2	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 2,025.00	5	Medium		
Park	6	Oak Park	4	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	5	There is no accessible route to the tennis courts.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	6	There is no accessible route to the benches.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	7	There is no accessible route to the picnic table.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	8	The top of the handrail gripping surface is not within a compliant range.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	9	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	10	There is no accessible route to the picnic table.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	11	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	12	There is no accessible route to the swings.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	13	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	14	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	15	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	16	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	17	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	18	There is no accessible route to the swings.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	19	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	20	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	6	Oak Park	21	There is no accessible route to the bench.	\$ 2,025.00	5	Medium		
Park	7	Millington Farmers Market	2	There is no accessible route to the gazebo.	\$ 1,350.00	5	Medium		
Park	7	Millington Farmers Market	9	There is no accessible route to the restrooms.	\$ 2,025.00	5	Medium		
Park	1	Aycock Park	4	The bridge has not been provided with edge protection.	\$ 1,350.00	6	Medium		
Park	1	Aycock Park	16	There is no accessible route to the (baseball fields).	\$ 4,725.00	6	Medium		
Park	1	Aycock Park	18	There is no accessible route to the (play ground areas).	\$ 2,025.00	6	Medium		
Park	1	Aycock Park	21	The wall sign is incorrectly located.	\$ 135.00	6	Medium		
Park	1	Aycock Park	22	The maneuvering clearance on the pull side of the door is not long enough in the direction of travel.	\$ 3,375.00	6	Medium		
Park	1	Aycock Park	27	The wall sign is incorrectly located.	\$ 135.00	6	Medium		
Park	1	Aycock Park	28	The toilet stall is not deep enough.	\$ 3,375.00	6	Medium		
Park	1	Aycock Park	34	The ramp run has not been provided with edge protection.	\$ 2,025.00	6	Medium		
Park	1	Aycock Park	35	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 4,050.00	6	Medium		
Park	1	Aycock Park	36	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by w	\$ 4,050.00	6	Medium		
Park	1	Aycock Park	37	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 4,050.00	6	Medium		
Park	1	Aycock Park	38	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 4,050.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	14	The van stall is missing a sign identifying it as a van accessible stall.	\$ 270.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	2	Biloxi Fields/Miles Baseball Park	17	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	18	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	19	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	20	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	21	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	22	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	23	The accessible route on the site contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.).	\$ 540.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	24	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	25	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	26	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	27	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	28	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	29	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	30	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	31	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	32	The utility box projects more than 4 inches into the circulation path.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	33	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	34	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 202.50	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	35	The curb ramp on the accessible route contains cross slopes greater than 2%.	\$ 2,025.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	36	The transition from the curb ramp to the walk, gutter or street is not flush and free of abrupt changes in level.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	38	The 30 inches minimum by 48 inches minimum clear floor space required at the bench is not flat (2% or 1:48 maximum slope) in all directions.	\$ 2,025.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	43	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	44	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	45	The knee clearance is not compliant.	\$ 3,375.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	50	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	54	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 16,200.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	55	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	59	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 16,200.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	60	The van stall is missing a sign identifying it as a van accessible stall.	\$ 270.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	61	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	64	There is no accessible route to the flag pole and surrounding benches.	\$ 1,350.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	67	There is no accessible route to the dugout.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	70	There is no accessible route to the dugout.	\$ 675.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	78	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	82	The restroom is not nearly compliant. No accessible toilet compartment, accessible urinal, accessible lavatory or accessible accessories (paper towel, etc.) is provided.	\$ 16,200.00	6	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	84	The restroom is not nearly compliant. No accessible toilet compartment, accessible lavatory or accessible accessories (paper towel, etc.) is provided.	\$ 16,200.00	6	Medium		
Park	3	Centennial Park	4	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	3	Centennial Park	6	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	3	Centennial Park	7	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	3	Centennial Park	8	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	3	Centennial Park	9	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	3	Centennial Park	10	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 2,025.00	6	Medium		
Park	3	Centennial Park	11	The drinking fountain is not accessible because there is not adequate clear floor space for an approach.	\$ 2,025.00	6	Medium		
Park	3	Centennial Park	12	The accessible path of travel contains cross slopes greater than 2%.	\$ 540.00	6	Medium		
Park	3	Centennial Park	13	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Park	3	Centennial Park	14	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Park	3	Centennial Park	15	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Park	3	Centennial Park	16	There is no accessible route to the tables and grill.	\$ 2,025.00	6	Medium		
Park	3	Centennial Park	17	There is no accessible route to the grill.	\$ 675.00	6	Medium		
Park	3	Centennial Park	18	There is no accessible route to the trash receptacle.	\$ 675.00	6	Medium		
Park	3	Centennial Park	19	There is no accessible route to the table.	\$ 675.00	6	Medium		
Park	3	Centennial Park	20	There is no accessible route to the table.	\$ 675.00	6	Medium		
Park	3	Centennial Park	21	There is no accessible route to the grill.	\$ 675.00	6	Medium		
Park	3	Centennial Park	22	There is no accessible route to the trash receptacle.	\$ 675.00	6	Medium		
Park	3	Centennial Park	23	There is no accessible route to the field.	\$ 2,025.00	6	Medium		
Park	3	Centennial Park	24	There is no accessible route to the trash receptacle.	\$ 675.00	6	Medium		
Park	3	Centennial Park	25	There is no accessible route to the table.	\$ 675.00	6	Medium		
Park	3	Centennial Park	26	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Park	3	Centennial Park	27	There is no accessible route to the trash receptacle.	\$ 675.00	6	Medium		
Park	3	Centennial Park	28	There is no accessible route to the soccer field.	\$ 2,025.00	6	Medium		
Park	3	Centennial Park	29	The trash receptacle is not accessible because there is not adequate clear floor space for an approach.	\$ 675.00	6	Medium		
Park	3	Centennial Park	30	The trash receptacle is not accessible because there is not adequate clear floor space for an approach.	\$ 675.00	6	Medium		
Park	3	Centennial Park	31	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Park	3	Centennial Park	32	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Park	3	Centennial Park	33	There is no accessible route to the bench.	\$ 675.00	6	Medium		
Park	3	Centennial Park	34	There is no accessible route to the field.	\$ 2,025.00	6	Medium		
Park	3	Centennial Park	35	The concrete expansion joint is spaced greater than a 1/2 inch.	\$ 675.00	6	Medium		
Park	3	Centennial Park	37	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 675.00	6	Medium		
Park	3	Centennial Park	39	The wall sign is mounted too low.	\$ 168.75	6	Medium		
Park	3	Centennial Park	40	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 16,200.00	6	Medium		
Park	3	Centennial Park	41	The wall sign is incorrectly located.	\$ 168.75	6	Medium		
Park	3	Centennial Park	42	There are not enough accessible toilet compartments. Where toilet compartments are provided, at least one toilet compartment shall be wheelchair accessible.	\$ 16,200.00	6	Medium		
Park	4	Joyner Fields	7	The wall sign is incorrectly located.	\$ 135.00	6	Medium		
Park	4	Joyner Fields	10	The wall sign is incorrectly located.	\$ 135.00	6	Medium		
Park	4	Joyner Fields	15	There is no accessible route to the (dugout).	\$ 2,025.00	6	Medium		
Park	4	Joyner Fields	16	There is no accessible route to the (practice area between the fields).	\$ 4,725.00	6	Medium		
Park	4	Joyner Fields	17	There is no accessible route to the (scorer's area).	\$ 2,025.00	6	Medium		
Park	4	Joyner Fields	18	There is no accessible route to the (scorer's area).	\$ 2,025.00	6	Medium		
Park	4	Joyner Fields	21	There is no accessible route to the (dugout).	\$ 2,025.00	6	Medium		
Park	4	Joyner Fields	22	There is no accessible route to the (flag pole).	\$ 2,025.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	4	Joyner Fields	23	There is no accessible route to the (swing set).	\$ 3,375.00	6	Medium		
Park	4	Joyner Fields	24	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	\$ 4,725.00	6	Medium		
Park	4	Joyner Fields	25	There is no accessible route to the (grill, picnic tables or benches).	\$ 6,750.00	6	Medium		
Park	5	Lions Park Pavillion	1	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Park	5	Lions Park Pavillion	2	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Park	5	Lions Park Pavillion	3	The parking sign is mounted too low.	\$ 202.50	6	Medium		
Park	7	Millington Farmers Market	4	The ramp does not have compliant handrails.	\$ 2,025.00	6	Medium		
Park	7	Millington Farmers Market	5	The ramp run has not been provided with edge protection.	\$ -	6	Medium		
Park	7	Millington Farmers Market	7	The ramp run has not been provided with edge protection.	\$ 2,025.00	6	Medium		
Park	7	Millington Farmers Market	8	The ramp does not have compliant handrails.	\$ -	6	Medium		
Park	7	Millington Farmers Market	11	The ramp run has not been provided with edge protection.	\$ 2,025.00	6	Medium		
Park	7	Millington Farmers Market	12	The ramp does not have compliant handrails.	\$ -	6	Medium		
Park	7	Millington Farmers Market	16	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Park	7	Millington Farmers Market	17	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Park	7	Millington Farmers Market	18	The restroom is not nearly compliant.	\$ 16,200.00	6	Medium		
Park	7	Millington Farmers Market	19	The tactile sign is incorrectly located.	\$ 168.75	6	Medium		
Park	1	Aycock Park	1	There is no accessible route to the (benches and tables).	\$ 1,350.00	7	Medium		
Park	1	Aycock Park	2	There is no accessible route to the (benches and tables).	\$ 1,350.00	7	Medium		
Park	1	Aycock Park	3	There is no accessible route to the (bridge).	\$ 1,012.50	7	Medium		
Park	1	Aycock Park	5	There is no accessible route to the (benches and tables).	\$ 1,350.00	7	Medium		
Park	1	Aycock Park	6	The required clear floor space is not deep enough. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	\$ 1,012.50	7	Medium		
Park	1	Aycock Park	7	The required clear floor space is not deep enough. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	\$ 1,012.50	7	Medium		
Park	1	Aycock Park	8	The accessible path of travel contains cross slopes greater than 2%.	\$ 1,890.00	7	Medium		
Park	1	Aycock Park	9	The required clear floor space is not deep enough. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	\$ 1,012.50	7	Medium		
Park	1	Aycock Park	10	The required clear floor space is not deep enough. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	\$ 1,012.50	7	Medium		
Park	1	Aycock Park	11	The accessible path of travel contains cross slopes greater than 2%.	\$ 3,375.00	7	Medium		
Park	1	Aycock Park	12	The required clear floor space is not deep enough. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	\$ 1,012.50	7	Medium		
Park	1	Aycock Park	13	The accessible path of travel contains cross slopes greater than 2%.	\$ 3,375.00	7	Medium		
Park	1	Aycock Park	14	The required clear floor space is not deep enough. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	\$ 1,012.50	7	Medium		
Park	1	Aycock Park	15	The accessible path of travel contains cross slopes greater than 2%.	\$ 4,050.00	7	Medium		
Park	1	Aycock Park	17	The route of travel at this location does not provide the required minimum width.	\$ 2,025.00	7	Medium		
Park	1	Aycock Park	19	Compliance with ASTM F 1951 for accessibility for ground surfaces on accessible routes, clear floor or ground spaces, and turning spaces has not been determined.	\$ 10,125.00	7	Medium		
Park	1	Aycock Park	20	There is no accessible route to the (play area).	\$ 2,025.00	7	Medium		
Park	1	Aycock Park	25	The faucet controls require twisting of the wrist.	\$ 337.50	7	Medium		
Park	1	Aycock Park	33	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch.	\$ 4,050.00	7	Medium		
Park	1	Aycock Park	39	The (outlet) is positioned too high for either a side or front approach.	\$ 675.00	7	Medium		
Park	1	Aycock Park	40	There is no accessible route to the (flag pole).	\$ 3,375.00	7	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	37	There are not enough drinking fountains. When drinking fountains are provided, a minimum of one must be designed for wheelchair users and one must be designed for standing persons unless a single fountain meets the requirements for both.	\$ 3,375.00	7	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	47	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	48	The sink is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	7	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	2	Biloxi Fields/Miles Baseball Park	51	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	56	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	77	There are not enough drinking fountains.	\$ 5,130.00	7	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	79	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Park	2	Biloxi Fields/Miles Baseball Park	80	The faucet controls require twisting of the wrist.	\$ 405.00	7	Medium		
Park	4	Joyner Fields	3	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	7	Medium		
Park	4	Joyner Fields	5	The (faucet) controls requires tight grasping, tight pinching or twisting of the wrist to operate.	\$ 337.50	7	Medium		
Park	5	Lions Park Pavilion	19	The trashcan is not positioned correctly for either a side or front approach.	\$ 108.00	7	Medium		
Park	6	Oak Park	3	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 108.00	7	Medium		
Park	7	Millington Farmers Market	13	The electrical outlet is positioned too high for either a side or front approach.	\$ 1,620.00	7	Medium		
Park	7	Millington Farmers Market	14	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 540.00	7	Medium		
Park	7	Millington Farmers Market	15	The electrical outlet is positioned too high for either a side or front approach.	\$ 810.00	7	Medium		
ROW Sidewalk	1	King Station Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 38,755.40	2	Medium		
ROW Sidewalk	2	Kelsey Lauren Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,795.95	2	Medium		
ROW Sidewalk	3	Queen Sinclair Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,340.65	2	Medium		
ROW Sidewalk	4	Pleasant Ridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,190.12	2	Medium		
ROW Sidewalk	5	Raleigh Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,576.34	2	Medium		
ROW Sidewalk	6	Pleasant Ridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 47,396.41	2	Medium		
ROW Sidewalk	7	Julia Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,028.02	2	Medium		
ROW Sidewalk	8	Zachary St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 34,265.60	2	Medium		
ROW Sidewalk	9	Colorday Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,663.79	2	Medium		
ROW Sidewalk	10	Eckois Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,876.23	2	Medium		
ROW Sidewalk	11	Tywaip Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,532.06	2	Medium		
ROW Sidewalk	12	Nichols Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,299.21	2	Medium		
ROW Sidewalk	13	Jeffery St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 48,716.74	2	Medium		
ROW Sidewalk	14	Ellen St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,978.42	2	Medium		
ROW Sidewalk	15	Annie Lee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,205.06	2	Medium		
ROW Sidewalk	16	Angie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,570.90	2	Medium		
ROW Sidewalk	17	Misslow Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,300.60	2	Medium		
ROW Sidewalk	18	Jack Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,184.05	2	Medium		
ROW Sidewalk	19	Barclay St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,285.56	2	Medium		
ROW Sidewalk	20	Karista St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,026.84	2	Medium		
ROW Sidewalk	21	Emmit St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,872.90	2	Medium		
ROW Sidewalk	22	Goldsby Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,042.23	2	Medium		
ROW Sidewalk	23	Cassell Dr / Juana Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 42,427.52	2	Medium		
ROW Sidewalk	24	Baywood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 114,239.56	2	Medium		
ROW Sidewalk	25	Tickle View Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 142,381.29	2	Medium		
ROW Sidewalk	26	Cedar Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40,378.56	2	Medium		
ROW Sidewalk	27	Clear Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 36,372.58	2	Medium		
ROW Sidewalk	28	Clear Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,789.36	2	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	29	Cedar Hills Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,989.19	2	Medium		
ROW Sidewalk	30	Black Gum Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,044.83	2	Medium		
ROW Sidewalk	31	S Honeysuckle Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,625.36	2	Medium		
ROW Sidewalk	32	Vincent Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,503.32	2	Medium		
ROW Sidewalk	33	Tamarack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30,506.81	2	Medium		
ROW Sidewalk	34	Hallbrook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,508.68	2	Medium		
ROW Sidewalk	35	Warcross Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,046.65	2	Medium		
ROW Sidewalk	36	Waycross Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,160.93	2	Medium		
ROW Sidewalk	37	Cades Brook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 95,108.00	2	Medium		
ROW Sidewalk	38	Cades Brook Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,422.84	2	Medium		
ROW Sidewalk	39	Cold Springs Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,425.91	2	Medium		
ROW Sidewalk	40	Richard Wilson Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 103,738.47	2	Medium		
ROW Sidewalk	41	Saddlebrook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,860.40	2	Medium		
ROW Sidewalk	42	Juana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 118,687.72	2	Medium		
ROW Sidewalk	43	Quay Hill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,722.90	2	Medium		
ROW Sidewalk	44	Pam Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 49,251.37	2	Medium		
ROW Sidewalk	45	Alder Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,409.31	2	Medium		
ROW Sidewalk	46	Alder Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 106,037.43	2	Medium		
ROW Sidewalk	47	Oak Harbor Trce	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70,837.37	2	Medium		
ROW Sidewalk	48	Balsa Glenn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 44,173.74	2	Medium		
ROW Sidewalk	49	Gunlock Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,139.86	2	Medium		
ROW Sidewalk	50	Blue Hills St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 32,943.58	2	Medium		
ROW Sidewalk	51	Sassy Tree Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,112.15	2	Medium		
ROW Sidewalk	52	W Honeysuckle Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,101.87	2	Medium		
ROW Sidewalk	53	Raleigh Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 224,381.86	2	Medium		
ROW Sidewalk	54	Prather St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,290.49	2	Medium		
ROW Sidewalk	55	Juana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 115,884.54	2	Medium		
ROW Sidewalk	56	Hallbrook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,387.47	2	Medium		
ROW Sidewalk	57	Pam Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 48,658.01	2	Medium		
ROW Sidewalk	58	Renda St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 75,062.15	2	Medium		
ROW Sidewalk	59	Baker St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 63,977.36	2	Medium		
ROW Sidewalk	60	Shella St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 27,738.92	2	Medium		
ROW Sidewalk	61	Dawson Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,327.87	2	Medium		
ROW Sidewalk	62	Thornhill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,078.75	2	Medium		
ROW Sidewalk	63	Big Creek Church Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,495.79	2	Medium		
ROW Sidewalk	64	Ryan Hill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 35,571.07	2	Medium		
ROW Sidewalk	65	Alexander Hill Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,683.08	2	Medium		
ROW Sidewalk	66	Bucknell Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,398.68	2	Medium		
ROW Sidewalk	67	Autumn Sun Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 44,387.15	2	Medium		
ROW Sidewalk	68	Eagles Hunt Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 44,515.35	2	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	69	Bennett Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 87,142.41	2	Medium		
ROW Sidewalk	70	Water Briar Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 89,526.70	2	Medium		
ROW Sidewalk	71	Logan's Path Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,010.70	2	Medium		
ROW Sidewalk	72	Oak Spring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 39,629.17	2	Medium		
ROW Sidewalk	73	Mary Lynn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 52,231.92	2	Medium		
ROW Sidewalk	74	Field Oak Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 47,353.38	2	Medium		
ROW Sidewalk	75	Tumbling Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 54,246.89	2	Medium		
ROW Sidewalk	76	Hickory Meadow	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 46,501.35	2	Medium		
ROW Sidewalk	77	Sweet Bark Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,042.26	2	Medium		
ROW Sidewalk	78	Trading Post Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,494.28	2	Medium		
ROW Sidewalk	79	Quito Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,798.13	2	Medium		
ROW Sidewalk	80	Oak Pebble Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,250.38	2	Medium		
ROW Sidewalk	81	Oak Pebble Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,763.55	2	Medium		
ROW Sidewalk	82	Quito Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,499.13	2	Medium		
ROW Sidewalk	83	Mary Lynn Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,768.76	2	Medium		
ROW Sidewalk	84	Chestnut Oak Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,079.22	2	Medium		
ROW Sidewalk	85	Oak Spring Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,645.11	2	Medium		
ROW Sidewalk	86	Babe Howard Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 56,178.99	2	Medium		
ROW Sidewalk	87	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 118,650.82	2	Medium		
ROW Sidewalk	88	Arapaho St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 57,737.07	2	Medium		
ROW Sidewalk	89	Tecumseh St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 105,647.32	2	Medium		
ROW Sidewalk	90	Wampum Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,873.73	2	Medium		
ROW Sidewalk	91	Kiowa St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 74,411.29	2	Medium		
ROW Sidewalk	92	Bill Knight Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 189,774.61	2	Medium		
ROW Sidewalk	93	Newport Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 52,038.46	2	Medium		
ROW Sidewalk	95	Rockford Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,345.78	2	Medium		
ROW Sidewalk	96	Doris Cir/ Saratoga Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 118,256.89	2	Medium		
ROW Sidewalk	97	Doris Cir/ Montgomery Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 101,447.28	2	Medium		
ROW Sidewalk	98	Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 156,725.26	2	Medium		
ROW Sidewalk	99	Church St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 65,888.81	2	Medium		
ROW Sidewalk	100	Raleigh Millington Rd/ Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 117,543.38	2	Medium		
ROW Sidewalk	101	Raleigh Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,521.04	2	Medium		
ROW Sidewalk	102	Salley Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,829.95	2	Medium		
ROW Sidewalk	103	Shelby Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,794.59	2	Medium		
ROW Sidewalk	104	Martha St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,992.69	2	Medium		
ROW Sidewalk	105	Talley Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,716.73	2	Medium		
ROW Sidewalk	106	Susan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,950.24	2	Medium		
ROW Sidewalk	107	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 187,515.81	2	Medium		
ROW Sidewalk	108	Easley Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 153,034.66	2	Medium		
ROW Sidewalk	109	Janie Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 72,748.78	2	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	110	Newport St/ Newport Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,669.75	2	Medium		
ROW Sidewalk	111	Max Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,065.34	2	Medium		
ROW Sidewalk	112	Janie Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,106.09	2	Medium		
ROW Sidewalk	114	Nelson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 88,689.91	2	Medium		
ROW Sidewalk	115	Laraine Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 49,319.82	2	Medium		
ROW Sidewalk	116	Harrold Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 81,246.98	2	Medium		
ROW Sidewalk	117	Harrold Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,282.12	2	Medium		
ROW Sidewalk	118	Buford Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 35,034.39	2	Medium		
ROW Sidewalk	119	Pryor St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,988.07	2	Medium		
ROW Sidewalk	120	Church St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,306.02	2	Medium		
ROW Sidewalk	121	School Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,483.64	2	Medium		
ROW Sidewalk	122	Quinn Circle	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,248.32	2	Medium		
ROW Sidewalk	123	C St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,739.70	2	Medium		
ROW Sidewalk	124	Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,946.64	2	Medium		
ROW Sidewalk	125	Easley Ave/ Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 27,264.07	2	Medium		
ROW Sidewalk	126	Navy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 106,217.52	2	Medium		
ROW Sidewalk	127	W Navy Circle	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60,725.76	2	Medium		
ROW Sidewalk	128	W National St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 198,621.15	2	Medium		
ROW Sidewalk	129	E National St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 28,964.67	2	Medium		
ROW Sidewalk	130	S Navy Circle	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 54,863.58	2	Medium		
ROW Sidewalk	131	Veterans Pky	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 89,132.59	2	Medium		
ROW Sidewalk	132	Dakar Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,651.14	2	Medium		
ROW Sidewalk	133	Astoria Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 61,390.55	2	Medium		
ROW Sidewalk	134	3rd Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,208.87	2	Medium		
ROW Sidewalk	135	B St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,705.28	2	Medium		
ROW Sidewalk	136	A St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,375.85	2	Medium		
ROW Sidewalk	137	School Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,275.54	2	Medium		
ROW Sidewalk	138	Wilkinsville Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 206,117.91	2	Medium		
ROW Sidewalk	139	Second Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 34,285.26	2	Medium		
ROW Sidewalk	140	North Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 84,283.73	2	Medium		
ROW Sidewalk	141	Cuba Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 56,984.54	2	Medium		
ROW Sidewalk	142	West St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 54,427.60	2	Medium		
ROW Sidewalk	143	Chambers St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 29,224.34	2	Medium		
ROW Sidewalk	144	Second Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60,646.82	2	Medium		
ROW Sidewalk	145	Bland Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 34,146.64	2	Medium		
ROW Sidewalk	146	Hill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,615.26	2	Medium		
ROW Sidewalk	147	First Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 37,811.78	2	Medium		
ROW Sidewalk	148	Cuba Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 49,707.26	2	Medium		
ROW Sidewalk	149	Densford Circle W	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,561.42	2	Medium		
ROW Sidewalk	150	Densford Circle E	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,488.77	2	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	151	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240,245.59	2	Medium		
ROW Sidewalk	152	Glencoe Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,628.21	2	Medium		
ROW Sidewalk	153	Wilkinsville Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 41,006.60	2	Medium		
ROW Sidewalk	154	Cooper Creek Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,425.94	2	Medium		
ROW Sidewalk	155	Creek Mill Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,028.02	2	Medium		
ROW Sidewalk	156	End Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,517.09	2	Medium		
ROW Sidewalk	157	Terrell Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 32,532.66	2	Medium		
ROW Sidewalk	158	Wells Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,650.26	2	Medium		
ROW Sidewalk	159	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 64,215.31	2	Medium		
ROW Sidewalk	160	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 248,082.25	2	Medium		
ROW Sidewalk	161	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 288,783.61	2	Medium		
ROW Sidewalk	162	Veterans Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 123,450.54	2	Medium		
ROW Sidewalk	163	Church St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,355.48	2	Medium		
ROW Sidewalk	164	Union Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 75,548.99	2	Medium		
ROW Sidewalk	165	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,050.62	2	Medium		
Signalized Intersection	1	Intersection of Babe Howard Blvd and Hwy 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Babe Howard Blvd and Hwy 51	\$ 82,200.00	5	Medium		
Signalized Intersection	3	Intersection of Church St and Veterans Pkwy	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Church St and Veterans Pkwy	\$ 33,900.00	5	Medium		
Signalized Intersection	7	Intersection of Navy Rd and Bethuel Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Bethuel Rd	\$ 78,700.00	5	Medium		
Signalized Intersection	8	Intersection of Navy Rd and Church St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Church St	\$ 62,700.00	5	Medium		
Signalized Intersection	9	Intersection of Navy Rd and Hornet Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Hornet Ave	\$ 78,500.00	5	Medium		
Signalized Intersection	10	Intersection of Navy Rd and Hwy 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Hwy 51	\$ 48,700.00	5	Medium		
Signalized Intersection	11	Intersection of Navy St and Veterans Pkwy	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy St and Veterans Pkwy	\$ 72,100.00	5	Medium		
Signalized Intersection	15	Intersection of Shelby Rd/ Easley Ave and Hwy 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Shelby Rd/ Easley Ave and Hwy 51	\$ 102,600.00	5	Medium		
Signalized Intersection	16	Intersection of Wilkinsville Rd and Hwy 51	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and Hwy 51	\$ 100,300.00	5	Medium		
Signalized Intersection	17	Intersection of Easley Ave and Nelson St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and Nelson St	\$ 54,900.00	5	Medium		
Unsignalized Intersection	1000	Intersection of King Station Rd and Kelsey Lauren Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of King Station Rd and Kelsey Lauren Cv	\$ 32,600.00	5	Medium		
Unsignalized Intersection	1001	Intersection of King Station Rd and Queen Sinclair Cir (East)	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of King Station Rd and Queen Sinclair Cir (East)	\$ 31,100.00	5	Medium		
Unsignalized Intersection	1002	Intersection of King Station Rd and Pleasant Ridge Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of King Station Rd and Pleasant Ridge Rd	\$ 45,200.00	5	Medium		
Unsignalized Intersection	1003	Intersection of King Station Rd and Queen Sinclair Cir (West)	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of King Station Rd and Queen Sinclair Cir (West)	\$ 47,000.00	5	Medium		
Unsignalized Intersection	1004	Intersection of King Station Rd and Raleigh Millington Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of King Station Rd and Raleigh Millington Rd	\$ 34,000.00	5	Medium		
Unsignalized Intersection	1006	Intersection of Pleasant Ridge Rd and Annie Lee St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Pleasant Ridge Rd and Annie Lee St	\$ 45,100.00	5	Medium		
Unsignalized Intersection	1007	Intersection of Pleasant Ridge Rd and Karista St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Pleasant Ridge Rd and Karista St	\$ 45,000.00	5	Medium		
Unsignalized Intersection	1008	Intersection of Annie Lee St and Zachary St / Julia Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Annie Lee St and Zachary St / Julia Cv	\$ 84,300.00	5	Medium		
Unsignalized Intersection	1009	Intersection of Angie St and Zachary St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Angie St and Zachary St	\$ 38,300.00	5	Medium		
Unsignalized Intersection	1010	Intersection of Barclay St and Zachary St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Barclay St and Zachary St	\$ 47,300.00	5	Medium		
Unsignalized Intersection	1011	Intersection of Karista St and Zachary St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Karista St and Zachary St	\$ 53,900.00	5	Medium		
Unsignalized Intersection	1012	Intersection of Emmit St and Zachary St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Emmit St and Zachary St	\$ 42,100.00	5	Medium		
Unsignalized Intersection	1013	Intersection of Jeffery St and Angie St / Misslow Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Jeffery St and Angie St / Misslow Cv	\$ 29,300.00	5	Medium		
Unsignalized Intersection	1014	Intersection of Barclay St and Tyler Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Barclay St and Tyler Cv	\$ 51,000.00	5	Medium		
Unsignalized Intersection	1015	Intersection of Emmit St and Tywalc Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Emmit St and Tywalc Cv	\$ 31,300.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Unsignalized Intersection	1016	Intersection of Raleigh Millington Rd and Ellen St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Ellen St	\$ 34,400.00	5	Medium		
Unsignalized Intersection	1017	Intersection of Annie Lee St and Ellen St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Annie Lee St and Ellen St	\$ 46,800.00	5	Medium		
Unsignalized Intersection	1018	Intersection of Jeffery St and Jack Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Jeffery St and Jack Cv	\$ 34,100.00	5	Medium		
Unsignalized Intersection	1019	Intersection of Emmit St and Nichols Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Emmit St and Nichols Cv	\$ 41,200.00	5	Medium		
Unsignalized Intersection	1020	Intersection of Jeffery St and Barclay St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Jeffery St and Barclay St	\$ 48,300.00	5	Medium		
Unsignalized Intersection	1021	Intersection of Jeffery St and Karista St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Jeffery St and Karista St	\$ 33,900.00	5	Medium		
Unsignalized Intersection	1022	Intersection of Jeffery St and Emmitt St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Jeffery St and Emmitt St	\$ 23,300.00	5	Medium		
Unsignalized Intersection	1023	Intersection of Raleigh Millington Rd and Goldsby Pl	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Goldsby Pl	\$ 37,800.00	5	Medium		
Unsignalized Intersection	1024	Intersection of Juana Dr and Bateman Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Bateman Rd	\$ 51,700.00	5	Medium		
Unsignalized Intersection	1025	Intersection of Juana Dr and Cassell Dr / Juana Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Cassell Dr / Juana Cv	\$ 82,600.00	5	Medium		
Unsignalized Intersection	1027	Intersection of Richard Wilson Dr and Baywood Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Richard Wilson Dr and Baywood Dr	\$ 79,500.00	5	Medium		
Unsignalized Intersection	1028	Intersection of Juana Dr and Baywood Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Baywood Dr	\$ 77,600.00	5	Medium		
Unsignalized Intersection	1029	Intersection of Baywood Dr and Alder Wood Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Baywood Dr and Alder Wood Dr	\$ 51,300.00	5	Medium		
Unsignalized Intersection	1030	Intersection of Cades Brook Dr and Baywood Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cades Brook Dr and Baywood Dr	\$ 49,200.00	5	Medium		
Unsignalized Intersection	1031	Intersection of Richard Wilson Dr and Tickle View Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Richard Wilson Dr and Tickle View Dr	\$ 76,100.00	5	Medium		
Unsignalized Intersection	1032	Intersection of Juana Dr and Tickle View Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Tickle View Dr	\$ 67,400.00	5	Medium		
Unsignalized Intersection	1033	Intersection of Tickle View Dr and Alder Wood Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Tickle View Dr and Alder Wood Dr	\$ 70,200.00	5	Medium		
Unsignalized Intersection	1034	Intersection of Cades Brook Dr and Tickle View Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cades Brook Dr and Tickle View Dr	\$ 53,700.00	5	Medium		
Unsignalized Intersection	1038	Intersection of Cedar Ridge Dr and Blue Hills St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cedar Ridge Dr and Blue Hills St	\$ 67,600.00	5	Medium		
Unsignalized Intersection	1042	Intersection of Raleigh Millington Rd and Cedar Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Cedar Ridge Dr	\$ 34,400.00	5	Medium		
Unsignalized Intersection	1045	Intersection of Cedar Hills Dr and Blue Hills St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cedar Hills Dr and Blue Hills St	\$ 56,700.00	5	Medium		
Unsignalized Intersection	1047	Intersection of Alder Wood Dr and Oak Harbour Trce	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Alder Wood Dr and Oak Harbour Trce	\$ 59,900.00	5	Medium		
Unsignalized Intersection	1049	Intersection of Oak Harbor Trce and Balsa Gelnn Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Oak Harbor Trce and Balsa Gelnn Dr	\$ 54,900.00	5	Medium		
Unsignalized Intersection	1050	Intersection of Blue Hills St and cul-de-sac	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Blue Hills St and cul-de-sac	\$ 5,100.00	5	Medium		
Unsignalized Intersection	1051	Intersection of Sassy Tree Ln and S Honeysuckle Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Sassy Tree Ln and S Honeysuckle Ln	\$ 56,000.00	5	Medium		
Unsignalized Intersection	1053	Intersection of S Honeysuckle Ln and cul-de-sac	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of S Honeysuckle Ln and cul-de-sac	\$ 7,800.00	5	Medium		
Unsignalized Intersection	1055	Intersection of Oak Harbor Trce and Gunlock Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Oak Harbor Trce and Gunlock Dr	\$ 54,500.00	5	Medium		
Unsignalized Intersection	1059	Intersection of Oak Harbor Trce and Sassy Tree Ln / Sassy Tree Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Oak Harbor Trce and Sassy Tree Ln / Sassy Tree Cv	\$ 75,800.00	5	Medium		
Unsignalized Intersection	1060	Intersection of Oak Harbor Trce and W Honeysuckle Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Oak Harbor Trce and W Honeysuckle Ln	\$ 49,100.00	5	Medium		
Unsignalized Intersection	1061	Intersection of Alder Wood Dr and Tamarack Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Alder Wood Dr and Tamarack Dr	\$ 54,500.00	5	Medium		
Unsignalized Intersection	1062	Intersection of Balsa Glenn Dr and Tamarack Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Balsa Glenn Dr and Tamarack Dr	\$ 64,100.00	5	Medium		
Unsignalized Intersection	1063	Intersection of Gunlock Dr and Tamarack Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Gunlock Dr and Tamarack Dr	\$ 54,200.00	5	Medium		
Unsignalized Intersection	1066	Intersection of Raleigh Millington Rd and Vincent Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Vincent Rd	\$ 41,600.00	5	Medium		
Unsignalized Intersection	1071	Intersection of Alder Wood Dr and Big Creek Church Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Alder Wood Dr and Big Creek Church Rd	\$ 54,600.00	5	Medium		
Unsignalized Intersection	1073	Intersection of Dawson Ridge Dr and Alexander Hill Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Dawson Ridge Dr and Alexander Hill Ln	\$ 26,500.00	5	Medium		
Unsignalized Intersection	1074	Intersection of Dawson Ridge Dr and Bucknell Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Dawson Ridge Dr and Bucknell Rd	\$ 42,000.00	5	Medium		
Unsignalized Intersection	1075	Intersection of Dawson Ridge Dr and Ryan Hill Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Dawson Ridge Dr and Ryan Hill Dr	\$ 17,200.00	5	Medium		
Unsignalized Intersection	1082	Intersection of Ryan Hill Dr and Alexander Hills Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Ryan Hill Dr and Alexander Hills Ln	\$ 56,000.00	5	Medium		
Unsignalized Intersection	1086	Intersection of Ryan Hill Dr and Thronhill Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Ryan Hill Dr and Thronhill Dr	\$ 46,800.00	5	Medium		
Unsignalized Intersection	1087	Intersection of Bucknell Rd and Thronhill Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bucknell Rd and Thronhill Dr	\$ 40,400.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Unsignalized Intersection	1092	Intersection of Big Creek Church Rd and Bucknell Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Big Creek Church Rd and Bucknell Rd	\$ 30,900.00	5	Medium		
Unsignalized Intersection	1098	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 50,400.00	5	Medium		
Unsignalized Intersection	1099	Intersection of Raleigh Millington Rd and Hwy 385 EB Frontage Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Hwy 385 EB Frontage Rd	\$ 38,100.00	5	Medium		
Unsignalized Intersection	1100	Intersection of Raleigh Millington Rd and Hwy 385 WB Frontage Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Hwy 385 WB Frontage Rd	\$ 23,000.00	5	Medium		
Unsignalized Intersection	1101	Intersection of Raleigh Millington Rd and Jones Boyd Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Jones Boyd Rd	\$ 20,100.00	5	Medium		
Unsignalized Intersection	1105	Intersection of Raleigh Millington Rd and Biloxi St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Biloxi St	\$ 31,100.00	5	Medium		
Unsignalized Intersection	1114	Intersection of Raleigh Millington Rd and Veterans Pkwy	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Veterans Pkwy	\$ 19,900.00	5	Medium		
Unsignalized Intersection	1123	Intersection of Church St and Bill Knight Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Church St and Bill Knight Rd	\$ 47,100.00	5	Medium		
Unsignalized Intersection	1124	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 12,600.00	5	Medium		
Unsignalized Intersection	1130	Intersection of Rockford Rd and Bill Knight Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Rockford Rd and Bill Knight Rd	\$ 53,100.00	5	Medium		
Unsignalized Intersection	1143	Intersection of Autumn Sun Rd and Trading Post Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Autumn Sun Rd and Trading Post Ln	\$ 33,600.00	5	Medium		
Unsignalized Intersection	1146	Intersection of Newport Rd and Saratoga Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Newport Rd and Saratoga Rd	\$ 48,100.00	5	Medium		
Unsignalized Intersection	1148	Intersection of Autumn Sun Rd and Eagles Hunt Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Autumn Sun Rd and Eagles Hunt Rd	\$ 49,300.00	5	Medium		
Unsignalized Intersection	1150	Intersection of Quito Rd and Autumn Sun Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Quito Rd and Autumn Sun Rd	\$ 49,200.00	5	Medium		
Unsignalized Intersection	1156	Intersection of Eagles Hunt Rd and Trading Post Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Eagles Hunt Rd and Trading Post Ln	\$ 48,600.00	5	Medium		
Unsignalized Intersection	1159	Intersection of Bennett Wood Dr and Sweet Bark Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bennett Wood Dr and Sweet Bark Rd	\$ 49,700.00	5	Medium		
Unsignalized Intersection	1160	Intersection of Eagles Hunt Rd and cul-de-sac	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Eagles Hunt Rd and cul-de-sac	\$ 34,200.00	5	Medium		
Unsignalized Intersection	1161	Intersection of Newport Rd and Montgomery Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Newport Rd and Montgomery Rd	\$ 63,000.00	5	Medium		
Unsignalized Intersection	1167	Intersection of Bennett Wood Dr and Trading Post Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bennett Wood Dr and Trading Post Ln	\$ 59,000.00	5	Medium		
Unsignalized Intersection	1174	Intersection of Water Briar Rd and Sweet Bark Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Water Briar Rd and Sweet Bark Rd	\$ 48,300.00	5	Medium		
Unsignalized Intersection	1178	Intersection of Bennett Wood Dr and Water Briar Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bennett Wood Dr and Water Briar Rd	\$ 48,800.00	5	Medium		
Unsignalized Intersection	1181	Intersection of Tumbling Creek Dr and Logans Path Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Tumbling Creek Dr and Logans Path Rd	\$ 42,700.00	5	Medium		
Unsignalized Intersection	1182	Intersection of Quito Rd and Bennett Wood Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Quito Rd and Bennett Wood Dr	\$ 43,400.00	5	Medium		
Unsignalized Intersection	1184	Intersection of Hickory Meadow Rd and Logans Path Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hickory Meadow Rd and Logans Path Rd	\$ 46,300.00	5	Medium		
Unsignalized Intersection	1190	Intersection of Navy Rd and E Navy Circle	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and E Navy Circle	\$ 31,100.00	5	Medium		
Unsignalized Intersection	1191	Intersection of Water Briar Rd and Trading Post Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Water Briar Rd and Trading Post Ln	\$ 46,200.00	5	Medium		
Unsignalized Intersection	1192	Intersection of Navy Rd and W Navy Circle	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and W Navy Circle	\$ 31,200.00	5	Medium		
Unsignalized Intersection	1194	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 5,700.00	5	Medium		
Unsignalized Intersection	1195	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 9,800.00	5	Medium		
Unsignalized Intersection	1199	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 8,500.00	5	Medium		
Unsignalized Intersection	1201	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 9,800.00	5	Medium		
Unsignalized Intersection	1202	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 9,800.00	5	Medium		
Unsignalized Intersection	1203	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 9,800.00	5	Medium		
Unsignalized Intersection	1205	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 1,800.00	5	Medium		
Unsignalized Intersection	1208	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 12,600.00	5	Medium		
Unsignalized Intersection	1211	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 4,400.00	5	Medium		
Unsignalized Intersection	1212	Intersection of Navy Rd and Greenlawn Pl	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Greenlawn Pl	\$ 28,300.00	5	Medium		
Unsignalized Intersection	1213	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 9,400.00	5	Medium		
Unsignalized Intersection	1217	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 7,300.00	5	Medium		
Unsignalized Intersection	1241	Intersection of Newport Rd and New Port Blvd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Newport Rd and New Port Blvd	\$ 58,600.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Unsignalized Intersection	1253	Intersection of Water Briar Rd and cul-de-sac	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Water Briar Rd and cul-de-sac	\$ 34,700.00	5	Medium		
Unsignalized Intersection	1262	Intersection of C St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of C St and driveway	\$ 6,300.00	5	Medium		
Unsignalized Intersection	1264	Intersection of Quito Rd and Quito Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Quito Rd and Quito Cv	\$ 42,800.00	5	Medium		
Unsignalized Intersection	1267	Intersection of C St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of C St and driveway	\$ 25,400.00	5	Medium		
Unsignalized Intersection	1276	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 16,500.00	5	Medium		
Unsignalized Intersection	1279	Intersection of Oak Spring Dr and Oak Spring Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Oak Spring Dr and Oak Spring Cv	\$ 45,000.00	5	Medium		
Unsignalized Intersection	1283	Intersection of Mary Lynn Dr and Mary Lynn Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Mary Lynn Dr and Mary Lynn Cv	\$ 52,800.00	5	Medium		
Unsignalized Intersection	1288	Intersection of Mary Lynn Dr and Oak Spring Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Mary Lynn Dr and Oak Spring Dr	\$ 55,500.00	5	Medium		
Unsignalized Intersection	1289	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 13,900.00	5	Medium		
Unsignalized Intersection	1290	Intersection of Quito Rd and Mary Lynn Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Quito Rd and Mary Lynn Dr	\$ 51,100.00	5	Medium		
Unsignalized Intersection	1301	Intersection of Easley Ave and Wilkinsville Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and Wilkinsville Rd	\$ 19,600.00	5	Medium		
Unsignalized Intersection	1303	Intersection of Mary Lynn Dr and Chestnut Oak Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Mary Lynn Dr and Chestnut Oak Cv	\$ 41,700.00	5	Medium		
Unsignalized Intersection	1305	Intersection of Nelson St and Laraine Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Nelson St and Laraine Dr	\$ 35,600.00	5	Medium		
Unsignalized Intersection	1319	Intersection of Nelson St and Janie Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Nelson St and Janie Ave	\$ 47,200.00	5	Medium		
Unsignalized Intersection	1322	Intersection of Quito Rd and Field Oak Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Quito Rd and Field Oak Rd	\$ 49,400.00	5	Medium		
Unsignalized Intersection	1325	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 15,200.00	5	Medium		
Unsignalized Intersection	1327	Intersection of Field Oak Rd and Oak Pebble Ln / Oak Pebble Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Field Oak Rd and Oak Pebble Ln / Oak Pebble Cv	\$ 84,000.00	5	Medium		
Unsignalized Intersection	1328	Intersection of Field Oak Rd and Mary Lynn Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Field Oak Rd and Mary Lynn Dr	\$ 46,100.00	5	Medium		
Unsignalized Intersection	1342	Intersection of Shelby Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Shelby Rd and driveway	\$ 20,900.00	5	Medium		
Unsignalized Intersection	1346	Intersection of Shelby Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Shelby Rd and driveway	\$ 20,900.00	5	Medium		
Unsignalized Intersection	1397	Intersection of North Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of North Ave and driveway	\$ 15,900.00	5	Medium		
Unsignalized Intersection	1431	Intersection of Glencoe Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Glencoe Rd and driveway	\$ 12,800.00	5	Medium		
Unsignalized Intersection	1435	Intersection of Glencoe Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Glencoe Rd and driveway	\$ 15,500.00	5	Medium		
Unsignalized Intersection	1438	Intersection of Wilkinsville Rd and Glencoe Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and Glencoe Rd	\$ 50,800.00	5	Medium		
Unsignalized Intersection	1439	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 15,900.00	5	Medium		
Unsignalized Intersection	1446	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 12,700.00	5	Medium		
Unsignalized Intersection	1450	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 18,200.00	5	Medium		
Unsignalized Intersection	1452	Intersection of Wilkinsville Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and driveway	\$ 31,200.00	5	Medium		
Unsignalized Intersection	1454	Intersection of Wells Rd and Terrell Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wells Rd and Terrell Ln	\$ 52,300.00	5	Medium		
Unsignalized Intersection	1456	Intersection of End Rd and Terrell Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of End Rd and Terrell Ln	\$ 43,200.00	5	Medium		
Unsignalized Intersection	1459	Intersection of Creek Mill Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Creek Mill Rd and driveway	\$ 31,500.00	5	Medium		
Unsignalized Intersection	1460	Intersection of End Rd and Wells Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of End Rd and Wells Rd	\$ 55,100.00	5	Medium		
Unsignalized Intersection	90002	Intersection of Ryan Hill Dr and Sandy Hollow Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Ryan Hill Dr and Sandy Hollow Ln	\$ 48,300.00	5	Medium		
Unsignalized Intersection	90003	Intersection of Bennett Wood Dr and Hickory Meadow Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bennett Wood Dr and Hickory Meadow Rd	\$ 74,100.00	5	Medium		
Unsignalized Intersection	90011	Intersection of Hwy 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and driveway	\$ 6,200.00	5	Medium		
Unsignalized Intersection	90013	Intersection of Hwy 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and driveway	\$ 9,800.00	5	Medium		
Unsignalized Intersection	90030	Intersection of Hwy 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and driveway	\$ 5,600.00	5	Medium		
Unsignalized Intersection	90082	Intersection of Veterans Pky and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Veterans Pky and driveway	\$ 56,400.00	5	Medium		
Unsignalized Intersection	90086	Intersection of Hwy 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and driveway	\$ 11,200.00	5	Medium		
Unsignalized Intersection	90087	Intersection of Hwy 51 and Bill Knight Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and Bill Knight Ave	\$ 66,100.00	5	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Unsignalized Intersection	90094	Intersection of Hwy 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Hwy 51 and driveway	\$ 10,300.00	5	Medium		
Unsignalized Intersection	90131	Intersection of C St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of C St and driveway	\$ 15,300.00	5	Medium		
Unsignalized Intersection	1005	Intersection of Raleigh Millington Rd and Pleasant Ridge Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Pleasant Ridge Rd	\$ 28,800.00	6	Medium		
Unsignalized Intersection	1026	Intersection of Raleigh Millington Rd and Bateman Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Bateman Rd	\$ 27,100.00	6	Medium		
Unsignalized Intersection	1035	Intersection of Raleigh Millington Rd and Cedar Rose Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Cedar Rose Dr	\$ 20,800.00	6	Medium		
Unsignalized Intersection	1036	Intersection of Juana Dr and Clear Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Clear Creek Dr	\$ 52,700.00	6	Medium		
Unsignalized Intersection	1037	Intersection of Cades Brook Dr and Clear Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cades Brook Dr and Clear Creek Dr	\$ 38,500.00	6	Medium		
Unsignalized Intersection	1039	Intersection of Cold Springs Ln and cul-de-sac	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cold Springs Ln and cul-de-sac	\$ 26,200.00	6	Medium		
Unsignalized Intersection	1040	Intersection of Richard Wilson Dr and Clear Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Richard Wilson Dr and Clear Creek Dr	\$ 38,400.00	6	Medium		
Unsignalized Intersection	1041	Intersection of Saddlebrook Dr and Clear Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Saddlebrook Dr and Clear Creek Dr	\$ 38,600.00	6	Medium		
Unsignalized Intersection	1043	Intersection of Juana Dr and Black Gum Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Black Gum Dr	\$ 39,100.00	6	Medium		
Unsignalized Intersection	1046	Intersection of Raleigh Millington Rd and Cedar Hills Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and Cedar Hills Dr	\$ 36,100.00	6	Medium		
Unsignalized Intersection	1048	Intersection of Cades Brook Dr and Cades Brook Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cades Brook Dr and Cades Brook Cv	\$ 38,700.00	6	Medium		
Unsignalized Intersection	1054	Intersection of Cades Brook Dr and Cold Springs Ln	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cades Brook Dr and Cold Springs Ln	\$ 38,900.00	6	Medium		
Unsignalized Intersection	1057	Intersection of Cold Springs Ln and Big Creek Church Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cold Springs Ln and Big Creek Church Rd	\$ 12,900.00	6	Medium		
Unsignalized Intersection	1058	Intersection of Juana Dr and Saddlebrook Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Saddlebrook Dr	\$ 39,100.00	6	Medium		
Unsignalized Intersection	1064	Intersection of Juana Dr and Quay Hill Dr / Richard Wilson Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Quay Hill Dr / Richard Wilson Dr	\$ 52,500.00	6	Medium		
Unsignalized Intersection	1067	Intersection of Vincent Dr and Vincent Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Vincent Dr and Vincent Cv	\$ 39,200.00	6	Medium		
Unsignalized Intersection	1068	Intersection of Pam Dr and Quay Hill Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Pam Dr and Quay Hill Dr	\$ 38,500.00	6	Medium		
Unsignalized Intersection	1069	Intersection of Vincent Dr and Prather St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Vincent Dr and Prather St	\$ 38,600.00	6	Medium		
Unsignalized Intersection	1070	Intersection of Juana Dr and Hallbrook Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Hallbrook Dr	\$ 39,000.00	6	Medium		
Unsignalized Intersection	1072	Intersection of Pam Dr and cul-de-sac	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Pam Dr and cul-de-sac	\$ 28,800.00	6	Medium		
Unsignalized Intersection	1077	Intersection of Baker St and Hallbrook Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Baker St and Hallbrook Dr	\$ 25,300.00	6	Medium		
Unsignalized Intersection	1078	Intersection of Juana Dr and Waycross Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Waycross Ave	\$ 45,800.00	6	Medium		
Unsignalized Intersection	1080	Intersection of Pam Dr and Waycross Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Pam Dr and Waycross Ave	\$ 25,300.00	6	Medium		
Unsignalized Intersection	1081	Intersection of Renda St and Waycross Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Renda St and Waycross Ave	\$ 31,800.00	6	Medium		
Unsignalized Intersection	1083	Intersection of Baker St and Waycross Ave	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Baker St and Waycross Ave	\$ 31,900.00	6	Medium		
Unsignalized Intersection	1089	Intersection of Pam Dr and Renda St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Pam Dr and Renda St	\$ 18,200.00	6	Medium		
Unsignalized Intersection	1091	Intersection of Juana Dr and Renda St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Renda St	\$ 45,700.00	6	Medium		
Unsignalized Intersection	1095	Intersection of Juana Dr and Baker St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Juana Dr and Baker St	\$ 39,000.00	6	Medium		
Unsignalized Intersection	1107	Intersection of Babe Howard Blvd and Arapaho St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Babe Howard Blvd and Arapaho St	\$ 40,000.00	6	Medium		
Unsignalized Intersection	1109	Intersection of Wampum Rd and Kiowa St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wampum Rd and Kiowa St	\$ 38,400.00	6	Medium		
Unsignalized Intersection	1110	Intersection of Arapaho St and Tecumseh St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Arapaho St and Tecumseh St	\$ 38,500.00	6	Medium		
Unsignalized Intersection	1111	Intersection of Babe Howard Blvd and Shangria Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Babe Howard Blvd and Shangria Dr	\$ 12,400.00	6	Medium		
Unsignalized Intersection	1115	Intersection of S Navy Circle and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of S Navy Circle and driveway	\$ 24,800.00	6	Medium		
Unsignalized Intersection	1117	Intersection of Tecumseh St and Wampum Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Tecumseh St and Wampum Rd	\$ 38,500.00	6	Medium		
Unsignalized Intersection	1118	Intersection of S Navy Circle and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of S Navy Circle and driveway	\$ 12,400.00	6	Medium		
Unsignalized Intersection	1129	Intersection of Bill Knight Ave and Arapaho St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bill Knight Ave and Arapaho St	\$ 38,900.00	6	Medium		
Unsignalized Intersection	1133	Intersection of Newport Rd and Bill Knight Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Newport Rd and Bill Knight Rd	\$ 24,700.00	6	Medium		
Unsignalized Intersection	1135	Intersection of Bill Knight Ave and Tecumseh St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bill Knight Ave and Tecumseh St	\$ 52,300.00	6	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Unsignalized Intersection	1136	Intersection of Bill Knight Ave and Kiowa St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bill Knight Ave and Kiowa St	\$ 39,000.00	6	Medium		
Unsignalized Intersection	1142	Intersection of Montgomery Rd and Saratoga Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Montgomery Rd and Saratoga Rd	\$ 38,000.00	6	Medium		
Unsignalized Intersection	1154	Intersection of Rockford Rd and Montgomery Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Rockford Rd and Montgomery Rd	\$ 51,200.00	6	Medium		
Unsignalized Intersection	1166	Intersection of Navy Rd and Attu St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Attu St	\$ 13,100.00	6	Medium		
Unsignalized Intersection	1183	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	1185	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	1187	Intersection of Navy Rd and National St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and National St	\$ 39,600.00	6	Medium		
Unsignalized Intersection	1200	Intersection of Navy Rd and Raleigh Millington Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and Raleigh Millington Rd	\$ 40,700.00	6	Medium		
Unsignalized Intersection	1209	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 10,200.00	6	Medium		
Unsignalized Intersection	1214	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 10,200.00	6	Medium		
Unsignalized Intersection	1222	Intersection of Navy Rd and South St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and South St	\$ 26,400.00	6	Medium		
Unsignalized Intersection	1240	Intersection of Navy Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	1266	Intersection of Salley Rd and Martha St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Salley Rd and Martha St	\$ 25,500.00	6	Medium		
Unsignalized Intersection	1275	Intersection of Easley Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and driveway	\$ 3,300.00	6	Medium		
Unsignalized Intersection	1281	Intersection of Newport Blvd and Max Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Newport Blvd and Max Dr	\$ 40,000.00	6	Medium		
Unsignalized Intersection	1284	Intersection of Buford Ave and Pryor St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Buford Ave and Pryor St	\$ 38,400.00	6	Medium		
Unsignalized Intersection	1291	Intersection of Buford Ave and Harrold Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Buford Ave and Harrold Dr	\$ 51,900.00	6	Medium		
Unsignalized Intersection	1293	Intersection of Susan Rd and Martha St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Susan Rd and Martha St	\$ 25,900.00	6	Medium		
Unsignalized Intersection	1300	Intersection of Janie Ave and Max Dr	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Janie Ave and Max Dr	\$ 38,600.00	6	Medium		
Unsignalized Intersection	1308	Intersection of Highway 51 and Talley Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and Talley Rd	\$ 37,500.00	6	Medium		
Unsignalized Intersection	1309	Intersection of Easley Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	1312	Intersection of Janie Ave and Janie Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Janie Ave and Janie Cv	\$ 38,600.00	6	Medium		
Unsignalized Intersection	1314	Intersection of Janie Ave and Jean Cv	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Janie Ave and Jean Cv	\$ 31,900.00	6	Medium		
Unsignalized Intersection	1326	Intersection of Talley Rd and Susan Rd	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Talley Rd and Susan Rd	\$ 37,800.00	6	Medium		
Unsignalized Intersection	1362	Intersection of School Ave and B St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of School Ave and B St	\$ 19,000.00	6	Medium		
Unsignalized Intersection	1366	Intersection of Second Ave and Chambers St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Second Ave and Chambers St	\$ 17,800.00	6	Medium		
Unsignalized Intersection	1378	Intersection of Bland Ave and Chambers St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Bland Ave and Chambers St	\$ 31,500.00	6	Medium		
Unsignalized Intersection	1391	Intersection of First Ave and Hill St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of First Ave and Hill St	\$ 24,700.00	6	Medium		
Unsignalized Intersection	1400	Intersection of North Ave and B St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of North Ave and B St	\$ 12,000.00	6	Medium		
Unsignalized Intersection	1408	Intersection of Cuba Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Cuba Millington Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	1443	Intersection of Wilkinsville Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	1447	Intersection of Wilkinsville Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	1449	Intersection of Wilkinsville Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	90080	Intersection of Harrold Dr and Pryor St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Harrold Dr and Pryor St	\$ 21,500.00	6	Medium		
Unsignalized Intersection	90089	Intersection of Navy Rd and C St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and C St	\$ 41,300.00	6	Medium		
Unsignalized Intersection	90132	Intersection of Martha St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Martha St and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	90141	Intersection of Wilkinsville Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Wilkinsville Rd and driveway	\$ 5,100.00	6	Medium		
Unsignalized Intersection	90142	Intersection of Easley Ave and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Easley Ave and driveway	\$ 3,300.00	6	Medium		
Unsignalized Intersection	90147	Intersection of Navy Rd and C St	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Navy Rd and C St	\$ 12,900.00	6	Medium		
Unsignalized Intersection	1451	Intersection of Highway 51 and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Highway 51 and driveway	\$ 9,900.00	8	Medium		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	2	Police Station - Jail - Courts	10	The (flag pole cleat) is positioned too high for either a side or front approach.	\$ 337.50	9	Low		
Building	2	Police Station - Jail - Courts	52	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	2	Police Station - Jail - Courts	53	The (paper towel dispenser) is positioned too high for either a side or front approach.	\$ 135.00	9	Low		
Building	2	Police Station - Jail - Courts	63	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	2	Police Station - Jail - Courts	64	The (paper towel dispenser) is positioned too high for either a side or front approach.	\$ 135.00	9	Low		
Building	2	Police Station - Jail - Courts	71	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	2	Police Station - Jail - Courts	73	The (paper towel dispenser) is positioned too high for either a side or front approach.	\$ 135.00	9	Low		
Building	2	Police Station - Jail - Courts	104	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	3	Millington Public Library	7	The rear grab bar is not a minimum 36 inches in length.	\$ 472.50	9	Low		
Building	3	Millington Public Library	9	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 202.50	9	Low		
Building	3	Millington Public Library	12	The rear grab bar is not a minimum 36 inches in length.	\$ 472.50	9	Low		
Building	3	Millington Public Library	14	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 202.50	9	Low		
Building	4	City Hall	16	The rear grab bar is not a minimum 36 inches in length.	\$ 472.50	9	Low		
Building	4	City Hall	17	The side grab bar does not extend far enough from the rear wall.	\$ 472.50	9	Low		
Building	4	City Hall	18	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 202.50	9	Low		
Building	4	City Hall	20	The (paper towel dispenser) projects more than 4 inches into the circulation path.	\$ 202.50	9	Low		
Building	4	City Hall	21	The compartment door is not self closing.	\$ 337.50	9	Low		
Building	4	City Hall	22	The coat hook is installed greater than 48 inches above the finished floor.	\$ 135.00	9	Low		
Building	4	City Hall	23	The water closet compartment door is missing a loop handle on the inside.	\$ 202.50	9	Low		
Building	4	City Hall	26	The rear grab bar is not a minimum 36 inches in length.	\$ 472.50	9	Low		
Building	4	City Hall	27	The side grab bar does not extend far enough from the rear wall.	\$ 472.50	9	Low		
Building	4	City Hall	28	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 202.50	9	Low		
Building	4	City Hall	30	The (paper towel dispenser) projects more than 4 inches into the circulation path.	\$ 202.50	9	Low		
Building	4	City Hall	31	The compartment door is not self closing.	\$ 337.50	9	Low		
Building	4	City Hall	32	The coat hook is installed greater than 48 inches above the finished floor.	\$ 135.00	9	Low		
Building	4	City Hall	33	The water closet compartment door is missing a loop handle on the inside.	\$ 202.50	9	Low		
Building	6	Baker Community Center	12	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 101.25	9	Low		
Building	6	Baker Community Center	13	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 202.50	9	Low		
Building	6	Baker Community Center	26	The paper towel dispenser's operation mechanism is too high off the floor.	\$ -	9	Low		
Building	6	Baker Community Center	27	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	6	Baker Community Center	31	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 101.25	9	Low		
Building	6	Baker Community Center	36	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 101.25	9	Low		
Building	6	Baker Community Center	37	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 202.50	9	Low		
Building	6	Baker Community Center	39	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 202.50	9	Low		
Building	6	Baker Community Center	46	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 202.50	9	Low		
Building	6	Baker Community Center	49	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 101.25	9	Low		
Building	6	Baker Community Center	52	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 101.25	9	Low		
Building	6	Baker Community Center	56	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	6	Baker Community Center	58	The coat hook is installed greater than 48 inches above the finished floor.	\$ 101.25	9	Low		
Building	6	Baker Community Center	59	The compartment door is not self closing.	\$ 135.00	9	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	6	Baker Community Center	60	The water closet compartment door is missing a loop handle.	\$ 405.00	9	Low		
Building	6	Baker Community Center	61	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	9	Low		
Building	6	Baker Community Center	62	The rear grab bar is not a minimum 36 inches in length.	\$ 540.00	9	Low		
Building	6	Baker Community Center	63	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	6	Baker Community Center	64	The paper towel dispenser's operation mechanism is too high off the floor.	\$ -	9	Low		
Building	6	Baker Community Center	65	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	6	Baker Community Center	66	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 101.25	9	Low		
Building	6	Baker Community Center	69	The door exceeds the maximum pressure to open the door.	\$ 135.00	9	Low		
Building	6	Baker Community Center	70	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	6	Baker Community Center	72	The coat hook is installed greater than 48 inches above the finished floor.	\$ 101.25	9	Low		
Building	6	Baker Community Center	73	The compartment door is not self closing.	\$ 202.50	9	Low		
Building	6	Baker Community Center	74	The water closet compartment door is missing a loop handle.	\$ 405.00	9	Low		
Building	6	Baker Community Center	75	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	9	Low		
Building	6	Baker Community Center	76	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	6	Baker Community Center	77	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ -	9	Low		
Building	6	Baker Community Center	78	The rear grab bar is not a minimum 36 inches in length.	\$ 540.00	9	Low		
Building	6	Baker Community Center	79	The operating hardware is not accessible because it requires tight grasping, pinching or twisting of the wrist to operate.	\$ 540.00	9	Low		
Building	7	USA Stadium Complex	71	The rim of the urinal is too high.	\$ 1,822.50	9	Low		
Building	7	USA Stadium Complex	73	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	7	USA Stadium Complex	80	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	7	USA Stadium Complex	84	The baby changing table operating mechanism is outside reach range.	\$ 405.00	9	Low		
Building	7	USA Stadium Complex	95	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	7	USA Stadium Complex	102	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	7	USA Stadium Complex	106	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	7	USA Stadium Complex	110	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	7	USA Stadium Complex	115	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	7	USA Stadium Complex	116	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	7	USA Stadium Complex	119	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	7	USA Stadium Complex	128	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	7	USA Stadium Complex	129	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	7	USA Stadium Complex	130	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	8	Millington Gym	14	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	8	Millington Gym	16	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	8	Millington Gym	22	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	8	Millington Gym	24	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	8	Millington Gym	29	The baby changing table operating mechanism is outside reach range.	\$ 405.00	9	Low		
Building	8	Millington Gym	30	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Building	8	Millington Gym	31	The side grab bar is not long enough.	\$ 540.00	9	Low		
Building	8	Millington Gym	38	The baby changing table operating mechanism is outside reach range.	\$ 405.00	9	Low		
Building	8	Millington Gym	39	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	8	Millington Gym	40	The side grab bar is not long enough.	\$ 540.00	9	Low		
Building	10	Millington Elementary School	68	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	69	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	70	The toilet paper dispenser is mounted too close to the top of the grab bar, minimizing the gripping surface.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	71	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	76	The rim of the urinal is too high.	\$ 1,822.50	9	Low		
Building	10	Millington Elementary School	81	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	83	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	84	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	87	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	88	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	90	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	93	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	94	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	99	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	100	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	111	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	112	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	113	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	115	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	117	The toilet paper dispenser does not allow a continuous flow.	\$ -	9	Low		
Building	10	Millington Elementary School	118	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	122	The vending machine is positioned too high for either a side or front approach.	\$ 270.00	9	Low		
Building	10	EA Harrold Elementary School	123	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	124	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	126	The coat hook is positioned too high for either a side or front approach.	\$ 101.25	9	Low		
Building	10	Millington Elementary School	128	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	132	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	EA Harrold Elementary School	150	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	EA Harrold Elementary School	168	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	200	The dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	235	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	240	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	10	EA Harrold Elementary School	246	The coat hook is positioned too high for either a side or front approach.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	266	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	267	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	270	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	271	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	276	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	277	The mirror is mounted too high.	\$ 135.00	9	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	10	Millington Elementary School	282	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	283	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	288	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	289	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	10	Millington Elementary School	294	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	10	Millington Elementary School	295	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	11	Millington Middle School	56	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 67.50	9	Low		
Building	11	Millington Middle School	59	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	70	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	82	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	9	Low		
Building	11	Millington Middle School	83	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	9	Low		
Building	11	Millington Middle School	87	The vision light panels (glazing/window) are mounted too high.	\$ 472.50	9	Low		
Building	11	Millington Middle School	96	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	97	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	103	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	105	The soap dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	129	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	134	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	145	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	11	Millington Middle School	181	The shelf projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	11	Millington Middle School	211	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	11	Millington Middle School	215	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	16	The flag pole operations is positioned too high for either a side or front approach.	\$ 270.00	9	Low		
Building	12	Millington Central High School	31	The flag pole operations is positioned too high for either a side or front approach.	\$ 270.00	9	Low		
Building	12	Millington Central High School	120	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	12	Millington Central High School	121	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	128	The paper towel dispensers projects more than 4 inches into the circulation path.	\$ 540.00	9	Low		
Building	12	Millington Central High School	134	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	137	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	138	The paper towel dispensers projects more than 4 inches into the circulation path.	\$ 540.00	9	Low		
Building	12	Millington Central High School	165	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	166	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ -	9	Low		
Building	12	Millington Central High School	171	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	172	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ -	9	Low		
Building	12	Millington Central High School	209	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	210	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ -	9	Low		
Building	12	Millington Central High School	216	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	217	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ -	9	Low		
Building	12	Millington Central High School	243	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	244	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ -	9	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	251	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	252	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ -	9	Low		
Building	12	Millington Central High School	263	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	12	Millington Central High School	265	The shower controls is positioned too high for either a side or front approach.	\$ 270.00	9	Low		
Building	12	Millington Central High School	272	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	290	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	295	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	315	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	12	Millington Central High School	319	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	12	Millington Central High School	321	The toilet paper is not installed within the compliant range.	\$ 270.00	9	Low		
Building	12	Millington Central High School	323	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	9	Low		
Building	12	Millington Central High School	341	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	345	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	350	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	352	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	12	Millington Central High School	353	The soap dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	360	The light switch is positioned too high for either a side or front approach.	\$ 270.00	9	Low		
Building	12	Millington Central High School	362	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	364	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	366	The light switch is positioned too high for either a side or front approach.	\$ 270.00	9	Low		
Building	12	Millington Central High School	370	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	372	The rim of the urinal is too high.	\$ 1,755.00	9	Low		
Building	12	Millington Central High School	378	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	383	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	387	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	388	The soap dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	389	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	12	Millington Central High School	416	The soap dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	417	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	12	Millington Central High School	418	The rim of the urinal is too high.	\$ 1,822.50	9	Low		
Building	12	Millington Central High School	423	The soap dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Building	12	Millington Central High School	424	The mirror is mounted too high.	\$ 135.00	9	Low		
Building	13	Millington-Memphis Airport	8	The water closet compartment door is missing a loop handle on the inside.	\$ 202.50	9	Low		
Building	13	Millington-Memphis Airport	9	The coat hook is installed greater than 48 inches above the finished floor.	\$ 135.00	9	Low		
Building	13	Millington-Memphis Airport	13	The coat hook is installed greater than 48 inches above the finished floor.	\$ 135.00	9	Low		
Building	13	Millington-Memphis Airport	14	The water closet compartment door is missing a loop handle on the inside.	\$ 202.50	9	Low		
Building	8	Millington Gym	5	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	10	Low		
Building	8	Millington Gym	6	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 135.00	10	Low		
Building	8	Millington Gym	9	The fire alarm projects more than 4 inches into the circulation path.	\$ 337.50	10	Low		
Building	8	Millington Gym	10	The fire alarm projects more than 4 inches into the circulation path.	\$ 337.50	10	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	8	Millington Gym	11	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 67.50	10	Low		
Building	12	Millington Central High School	343	The 30 inches minimum by 48 inches minimum clear floor space required at the concession stand is not flat (2% or 1:48 maximum slope) in all directions.	\$ 1,350.00	10	Low		
Building	1	County Clerk Office/Fire Station #1	38	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	11	Low		
Building	1	County Clerk Office/Fire Station #1	54	There are not enough accessible special holding/housing cells with the required mobility features.	\$ -	11	Low		
Building	1	County Clerk Office/Fire Station #1	55	There is no accessible route to the (bay area).	\$ 3,375.00	11	Low		
Building	1	County Clerk Office/Fire Station #1	58	There is no accessible route to the (weight room).	\$ 4,725.00	11	Low		
Building	1	County Clerk Office/Fire Station #1	59	The restroom is not nearly compliant.	\$ 13,500.00	11	Low		
Building	1	County Clerk Office/Fire Station #1	61	The kitchen counter top is too high.	\$ 3,375.00	11	Low		
Building	1	County Clerk Office/Fire Station #1	62	Knee and toe space has not been provided at the sink.	\$ -	11	Low		
Building	1	County Clerk Office/Fire Station #1	63	The controls are located such that operation require reaching across burners.	\$ 3,375.00	11	Low		
Building	1	County Clerk Office/Fire Station #1	64	The (hood vent controls) are positioned too high for either a side or front approach.	\$ 675.00	11	Low		
Building	7	USA Stadium Complex	88	The knee clearance not compliant.	\$ 3,375.00	11	Low		
Building	10	EA Harrold Elementary School	136	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 67.50	11	Low		
Building	10	EA Harrold Elementary School	142	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	11	Low		
Building	10	EA Harrold Elementary School	146	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	11	Low		
Building	10	EA Harrold Elementary School	147	The mirror is mounted too high.	\$ 135.00	11	Low		
Building	10	EA Harrold Elementary School	148	The soap dispenser's operation mechanism is too high off the floor.	\$ 270.00	11	Low		
Building	10	EA Harrold Elementary School	149	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	11	Low		
Building	10	EA Harrold Elementary School	151	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	11	Low		
Building	10	EA Harrold Elementary School	152	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375.00	11	Low		
Building	10	EA Harrold Elementary School	153	The door/gate operating hardware is not accessible.	\$ 506.25	11	Low		
Building	10	EA Harrold Elementary School	154	The restroom is not nearly compliant.	\$ 16,200.00	11	Low		
Building	10	EA Harrold Elementary School	155	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	11	Low		
Building	10	EA Harrold Elementary School	157	The water and drain pipes under the lavatory are not adequately insulated.	\$ 135.00	11	Low		
Building	10	EA Harrold Elementary School	158	The restroom is not nearly compliant.	\$ 16,200.00	11	Low		
Building	10	EA Harrold Elementary School	170	Compliant knee space has not been provided under the lavatory.	\$ 3,375.00	11	Low		
Building	10	EA Harrold Elementary School	171	The mirror is mounted too high.	\$ 135.00	11	Low		
Building	10	EA Harrold Elementary School	172	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	11	Low		
Building	10	EA Harrold Elementary School	173	The restroom is not nearly compliant.	\$ 4,050.00	11	Low		
Building	10	EA Harrold Elementary School	220	The vending machine controls is positioned too high for either a side or front approach.	\$ -	11	Low		
Building	11	Millington Middle School	63	The restroom is not nearly compliant.	\$ 10,800.00	11	Low		
Building	11	Millington Middle School	64	The restroom is not nearly compliant.	\$ 10,800.00	11	Low		
Building	11	Millington Middle School	107	The top of the sink is too high.	\$ 2,700.00	11	Low		
Building	11	Millington Middle School	108	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	11	Low		
Building	11	Millington Middle School	109	The restroom is not nearly compliant.	\$ 4,050.00	11	Low		
Building	12	Millington Central High School	75	The kitchen counter top is too high.	\$ 2,700.00	11	Low		
Building	12	Millington Central High School	79	The flush handle is located on the wrong side of the toilet.	\$ 1,350.00	11	Low		
Building	12	Millington Central High School	80	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 202.50	11	Low		
Building	12	Millington Central High School	81	The restroom is not nearly compliant.	\$ 2,025.00	11	Low		
Building	12	Millington Central High School	82	The restroom is not nearly compliant.	\$ 2,025.00	11	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Millington Central High School	85	The kitchen counter top is too high.	\$ 2,700.00	11	Low		
Building	12	Millington Central High School	86	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	11	Low		
Building	12	Millington Central High School	89	The top rim of the lavatory is too high.	\$ 2,700.00	11	Low		
Building	12	Millington Central High School	90	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	11	Low		
Building	12	Millington Central High School	91	The flush handle is located on the wrong side of the toilet.	\$ 2,025.00	11	Low		
Building	12	Millington Central High School	92	The restroom is not nearly compliant.	\$ 4,050.00	11	Low		
Building	12	Millington Central High School	93	The mirror is mounted too high.	\$ 135.00	11	Low		
Building	12	Millington Central High School	140	The kitchen counter top is too high.	\$ 2,700.00	11	Low		
Building	12	Millington Central High School	142	The mirror is mounted too high.	\$ 135.00	11	Low		
Building	12	Millington Central High School	143	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	11	Low		
Building	12	Millington Central High School	144	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	11	Low		
Building	12	Millington Central High School	145	The lavatory's clear floor space is obstructed by the paper towel dispenser.	\$ -	11	Low		
Building	12	Millington Central High School	146	The coat hook is installed greater than 48 inches above the finished floor.	\$ 135.00	11	Low		
Building	12	Millington Central High School	147	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	11	Low		
Building	12	Millington Central High School	148	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	11	Low		
Building	12	Millington Central High School	149	The lavatory's clear floor space is obstructed by the paper towel dispenser.	\$ -	11	Low		
Building	12	Millington Central High School	150	The mirror is mounted too high.	\$ 135.00	11	Low		
Building	12	Millington Central High School	176	The walking surface is obstructed. A 36 inch minimum clear walking surface is required.	\$ 2,025.00	11	Low		
Building	12	Millington Central High School	177	The kitchen counter top is too high.	\$ 2,700.00	11	Low		
Building	12	Millington Central High School	178	The faucet controls is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 405.00	11	Low		
Building	12	Millington Central High School	179	The mirror is mounted too high.	\$ 135.00	11	Low		
Building	12	Millington Central High School	180	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 202.50	11	Low		
Building	12	Millington Central High School	181	The toilet is not located within the range allowed from the side wall or partition.	\$ 2,700.00	11	Low		
Building	12	Millington Central High School	182	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	11	Low		
Building	12	Millington Central High School	183	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	11	Low		
Building	12	Millington Central High School	184	The lavatory's clear floor space is obstructed by the paper towel dispenser.	\$ -	11	Low		
Building	12	Millington Central High School	185	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side.	\$ 202.50	11	Low		
Building	12	Millington Central High School	186	The mirror is mounted too high.	\$ 135.00	11	Low		
Building	12	Millington Central High School	187	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075.00	11	Low		
Building	12	Millington Central High School	188	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 270.00	11	Low		
Building	12	Millington Central High School	189	The coat hook is installed greater than 48 inches above the finished floor.	\$ 135.00	11	Low		
Building	12	Millington Central High School	190	The lavatory's clear floor space is obstructed by the paper towel dispenser.	\$ -	11	Low		
Building	12	Millington Central High School	191	The toilet is not located within the range allowed from the side wall or partition.	\$ 2,700.00	11	Low		
Building	13	Millington-Memphis Airport	22	Knee and toe space has not been provided at the sink.	\$ 3,375.00	11	Low		
Building	13	Millington-Memphis Airport	23	The controls are located such that operation require reaching across burners.	\$ 3,375.00	11	Low		
Building	13	Millington-Memphis Airport	24	The (paper towel and soap dispenser) is positioned too high for either a side or front approach. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the fi	\$ 202.50	11	Low		
Building	13	Millington-Memphis Airport	25	The (hood vent controls) are positioned too high for either a side or front approach.	\$ 675.00	11	Low		
Building	13	Millington-Memphis Airport	26	There are no accessible bathing or shower facilities.	\$ 3,375.00	11	Low		
Building	13	Millington-Memphis Airport	27	The toilet paper is not installed within the compliant range in front of the toilet.	\$ 202.50	11	Low		
Building	13	Millington-Memphis Airport	28	The coat hook is installed greater than 48 inches above the finished floor.	\$ 135.00	11	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	13	Millington-Memphis Airport	29	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	11	Low		
Building	13	Millington-Memphis Airport	30	The maneuvering space on the pull side of the door does not adequately extend beyond the latch side of the door.	\$ 3,375.00	11	Low		
Building	13	Millington-Memphis Airport	31	The ramp does not have protection against wheel entrapment.	\$ 3,375.00	11	Low		
Building	13	Millington-Memphis Airport	32	The ramp does not have compliant handrails.	\$ 3,375.00	11	Low		
Building	13	Millington-Memphis Airport	33	The landing at the door has a closer and does not provide compliant latch side clearance.	\$ 3,375.00	11	Low		
Building	12	Millington Central High School	250	The room contains 6 or more fixtures and therefore must have a minimum of one ambulatory toilet stall. Where six or more compartments are provided, or where the combination of urinals and water closets totals six or more fixtures within a multiple-accom	\$ 3,375.00	12	Low		
Building	12	Millington Central High School	431	The restroom is not nearly compliant.	\$ 4,050.00	12	Low		
Park	1	Aycock Park	23	The compartment door is not self closing.	\$ 135.00	9	Low		
Park	1	Aycock Park	24	The water closet compartment door is missing a loop handle on the inside.	\$ 202.50	9	Low		
Park	1	Aycock Park	26	The (paper towel dispenser) is positioned too high for either a side or front approach.	\$ 135.00	9	Low		
Park	1	Aycock Park	29	The water closet compartment door is missing loop handles.	\$ 270.00	9	Low		
Park	1	Aycock Park	30	The compartment door is not self closing.	\$ 135.00	9	Low		
Park	1	Aycock Park	31	The (paper towel dispenser) is positioned too high for either a side or front approach.	\$ 135.00	9	Low		
Park	2	Biloxi Fields/Miles Baseball Park	52	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Park	2	Biloxi Fields/Miles Baseball Park	53	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
Park	2	Biloxi Fields/Miles Baseball Park	57	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 270.00	9	Low		
Park	2	Biloxi Fields/Miles Baseball Park	58	The paper towel dispenser is not accessible because it requires tight grasping, pinching or twisting of the wrist.	\$ 540.00	9	Low		
ROW Sidewalk	1	King Station Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30,634.70	3	Low		
ROW Sidewalk	3	Queen Sinclair Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 31,440.54	3	Low		
ROW Sidewalk	4	Pleasant Ridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 421.01	3	Low		
ROW Sidewalk	7	Julia Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,814.24	3	Low		
ROW Sidewalk	8	Zachary St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,746.06	3	Low		
ROW Sidewalk	9	Colorday Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,949.50	3	Low		
ROW Sidewalk	10	Eckois Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,174.60	3	Low		
ROW Sidewalk	11	Tywaip Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,705.63	3	Low		
ROW Sidewalk	12	Nichols Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,963.65	3	Low		
ROW Sidewalk	13	Jeffery St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,127.86	3	Low		
ROW Sidewalk	15	Annie Lee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,440.01	3	Low		
ROW Sidewalk	16	Angie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,238.90	3	Low		
ROW Sidewalk	17	Misslow Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,668.57	3	Low		
ROW Sidewalk	18	Jack Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,714.99	3	Low		
ROW Sidewalk	19	Barclay St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,651.35	3	Low		
ROW Sidewalk	20	Karista St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,698.90	3	Low		
ROW Sidewalk	22	Goldsby Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,598.67	3	Low		
ROW Sidewalk	26	Cedar Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,342.17	3	Low		
ROW Sidewalk	27	Clear Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,050.71	3	Low		
ROW Sidewalk	29	Cedar Hills Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30,129.94	3	Low		
ROW Sidewalk	32	Vincent Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,322.56	3	Low		
ROW Sidewalk	33	Tamarack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,954.25	3	Low		
ROW Sidewalk	35	Warcross Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,297.19	3	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	37	Cades Brook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,610.61	3	Low		
ROW Sidewalk	38	Cades Brook Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,804.45	3	Low		
ROW Sidewalk	39	Cold Springs Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,507.60	3	Low		
ROW Sidewalk	40	Richard Wilson Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,148.51	3	Low		
ROW Sidewalk	41	Saddlebrook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 735.33	3	Low		
ROW Sidewalk	42	Juana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,156.78	3	Low		
ROW Sidewalk	46	Alder Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,532.80	3	Low		
ROW Sidewalk	47	Oak Harbor Trce	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,870.41	3	Low		
ROW Sidewalk	49	Gunlock Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,787.58	3	Low		
ROW Sidewalk	50	Blue Hills St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,521.66	3	Low		
ROW Sidewalk	51	Sassy Tree Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,179.56	3	Low		
ROW Sidewalk	53	Raleigh Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,008.95	3	Low		
ROW Sidewalk	54	Prather St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,704.46	3	Low		
ROW Sidewalk	55	Juana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,542.04	3	Low		
ROW Sidewalk	57	Pam Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,747.09	3	Low		
ROW Sidewalk	58	Renda St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,948.39	3	Low		
ROW Sidewalk	59	Baker St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,679.14	3	Low		
ROW Sidewalk	68	Eagles Hunt Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,655.49	3	Low		
ROW Sidewalk	69	Bennett Wood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,070.05	3	Low		
ROW Sidewalk	70	Water Briar Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,105.97	3	Low		
ROW Sidewalk	72	Oak Spring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,489.59	3	Low		
ROW Sidewalk	73	Mary Lynn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,314.30	3	Low		
ROW Sidewalk	74	Field Oak Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,512.87	3	Low		
ROW Sidewalk	75	Tumbling Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,382.09	3	Low		
ROW Sidewalk	76	Hickory Meadow	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,222.12	3	Low		
ROW Sidewalk	78	Trading Post Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,768.80	3	Low		
ROW Sidewalk	79	Quito Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,451.60	3	Low		
ROW Sidewalk	82	Quito Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,375.78	3	Low		
ROW Sidewalk	83	Mary Lynn Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,547.60	3	Low		
ROW Sidewalk	85	Oak Spring Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,628.78	3	Low		
ROW Sidewalk	88	Arapaho St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,716.74	3	Low		
ROW Sidewalk	89	Tecumseh St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,472.38	3	Low		
ROW Sidewalk	91	Kiowa St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,602.40	3	Low		
ROW Sidewalk	92	Bill Knight Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 56,501.50	3	Low		
ROW Sidewalk	93	Newport Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,771.39	3	Low		
ROW Sidewalk	96	Doris Cir/ Saratoga Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,756.82	3	Low		
ROW Sidewalk	97	Doris Cir/ Montgomery Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,507.58	3	Low		
ROW Sidewalk	104	Martha St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,147.25	3	Low		
ROW Sidewalk	107	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,296.84	3	Low		
ROW Sidewalk	108	Easley Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,489.36	3	Low		

Facility Type	GPS ID	Project Name	Barrier #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
ROW Sidewalk	109	Janie Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,429.06	3	Low		
ROW Sidewalk	111	Max Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,834.66	3	Low		
ROW Sidewalk	112	Janie Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,412.75	3	Low		
ROW Sidewalk	113	Jean Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,174.62	3	Low		
ROW Sidewalk	114	Nelson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,309.65	3	Low		
ROW Sidewalk	115	Laraine Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,767.41	3	Low		
ROW Sidewalk	116	Harrold Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,096.98	3	Low		
ROW Sidewalk	117	Harrold Cv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,217.88	3	Low		
ROW Sidewalk	119	Pryor St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,913.90	3	Low		
ROW Sidewalk	123	C St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,728.95	3	Low		
ROW Sidewalk	127	W Navy Circle	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,395.22	3	Low		
ROW Sidewalk	139	Second Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,686.84	3	Low		
ROW Sidewalk	141	Cuba Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,454.36	3	Low		
ROW Sidewalk	144	Second Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,252.46	3	Low		
ROW Sidewalk	147	First Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,639.46	3	Low		
ROW Sidewalk	148	Cuba Millington Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,108.71	3	Low		
ROW Sidewalk	151	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,720.53	3	Low		
ROW Sidewalk	153	Wilkinsville Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,555.19	3	Low		
ROW Sidewalk	154	Cooper Creek Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,020.61	3	Low		
ROW Sidewalk	156	End Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,874.15	3	Low		
ROW Sidewalk	157	Terrell Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,310.29	3	Low		
ROW Sidewalk	158	Wells Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,810.55	3	Low		
ROW Sidewalk	164	Union Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,684.31	3	Low		
ROW Sidewalk	165	Highway 51	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,849.38	3	Low		
Unsignalized Intersection	1052	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1056	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1085	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1088	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 2,700.00	13	Low		
Unsignalized Intersection	1094	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1097	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1102	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1103	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1104	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1106	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1112	Intersection of Biloxi St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Biloxi St and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1116	Intersection of Biloxi St and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Biloxi St and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1120	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1121	Intersection of W Navy Circle and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of W Navy Circle and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1122	Intersection of Raleigh Millington Rd and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of Raleigh Millington Rd and driveway	\$ 1,400.00	13	Low		
Unsignalized Intersection	1125	Intersection of E Navy Circle and driveway	N/A	See facility report and GIS data for detailed evaluation findings at the Intersection of E Navy Circle and driveway	\$ 1,400.00	13	Low		

